Document 18

Filed 02/28/25

Page 1 of 91 Page ID

Case 2:24-cv-09153-HDV-AS

knowledge as to their own facts and upon information and belief and the investigation of counsel as to all other matters.

INTRODUCTION

- 1. This is a class action lawsuit brought by Plaintiffs on behalf of themselves and a class of current and former Honda vehicle owners and lessees of model years ("MY") 2018-2021 Honda Odyssey vehicles (the "Class Vehicles" or "Vehicles").
- 2. This action arises from Honda's failure, despite its longstanding knowledge of this material and manufacturing defect, to disclose to Plaintiffs and other consumers that the Class Vehicles suffer from a defective body seam seal that cracks, fails, and thereby allows water to infiltrate the rear driver's side panel of the Class Vehicles. The body seam seal, *inter alia*, protects the control module for the power tailgate (i.e. a motorized trunk) from outside elements including water. Thus, when the body seam seal fails, water infiltrates through the defective seal, allowing water to come into contact with the control unit and causes the power tailgate to malfunction and/or fail (the "Sealant Defect" or "Defect").
- 3. Significantly, a malfunctioning power tailgate opens and closes at random, including when the Class Vehicles are being driven, presenting a serious safety concern. In addition, the power tailgate can fail to either open or close, preventing the owners of the Class Vehicles with access to the trunk and, in the case of a power tailgate failing to close, preventing the Class Vehicles from being safely operated and stranding their owners. As described below, the malfunctioning tailgate can also lead to short circuits and fires, as well as mold growth.
- 4. Not only did Honda actively conceal the fact that the Class Vehicles' body seam seals were defective (and require costly repairs to fix), it did not reveal that the existence of this defect would diminish the intrinsic and resale value of the Class Vehicles.

¹ Plaintiffs reserve the right to amend or add to the vehicle models included in the definition of Class Vehicles after conducting discovery.

4

5

- 6
- 7 8
- 9

10

- 11
- 12
- SANTA BARBARA, CALIFORNIA 93101 13 14
- 15
- 16
- 17 18
- 20

19

- 21 22
- 23

24

- 25
- 26 27
- 28

- 5. Honda has long been aware of the Sealant Defect. Despite its longstanding knowledge of this defect, Honda has failed to adequately repair the Class Vehicles when the defect manifests.
- Many owners and lessees of Class Vehicles have communicated with 6. Defendants and their agents to request that Honda remedy and/or address the Sealant Defect and resultant damage at no expense. Defendants have failed and/or refused to do so – often conveying to Class Vehicle owners and lessees that Class Vehicles are operating as intended and therefore cannot be repaired under warranty or otherwise.
- For customers whose Vehicles are within the New Vehicle Limited Warranty period (which extends for the shorter of three years or 36,000 miles), Honda has done nothing to address or correct the Sealant Defect when it manifests in the Class Vehicles.
- 8. Despite notice and knowledge of the Sealant Defect from the numerous consumer complaints it has received, information received from Honda dealerships, pre-sale durability testing, National Highway Traffic Safety Administration ("NHTSA") complaints, and its own internal records, Honda has not recalled the Class Vehicles to repair the Sealant Defect, offered its customers a suitable repair or replacement free of charge, or offered to reimburse its customers who have incurred out-of-pocket expenses to repair the Sealant Defect.
- 9. As a result of Honda's unfair, deceptive and/or fraudulent business practices, owners and/or lessees of Class Vehicles, including Plaintiffs, have suffered an ascertainable loss of money and/or property and/or loss in value. The unfair and deceptive trade practices committed by Honda were conducted in a manner giving rise to substantial aggravating circumstances.
- 10. Had Plaintiffs and other Class members known about the Sealant Defect at the time of purchase or lease, they would not have purchased or leased the Class Vehicles, or would have paid substantially less for the Class Vehicles.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

- 11. As a result of the Sealant Defect and the considerable monetary costs associated with attempting to repair such defect, Plaintiffs and other Class members have suffered injury in fact, incurred damages and have otherwise been harmed by Honda's conduct.
- 12. Accordingly, Plaintiffs bring this action to redress Honda's violations of the California Consumers Legal Remedies Act, California Unfair Competition Law, Florida Deceptive and Unfair Trade Practices Act, Maryland Consumer Protection Act, New Jersey Consumer Fraud Act, Washington Consumer Protection Act, and also to seek recovery for Honda's breach of express warranty, breach of implied warranty, common law fraud, breach of the covenant of good faith and fair dealing and, alternatively, unjust enrichment.

JURISDICTION AND VENUE

- 13. This Court has subject matter jurisdiction over this action pursuant to 28 U.S.C. §1332 of the Class Action Fairness Act of 2005 because: (i) there are 100 or more class members, (ii) there is an aggregate amount in controversy exceeding \$5,000,000, exclusive of interest and costs, and (iii) there is minimal diversity because at least one plaintiff and one defendant are citizens of different states. This Court has supplemental jurisdiction over the state law claims pursuant to 28 U.S.C. § 1367.
- 14. Venue is proper in this judicial district pursuant to 28 U.S.C. §1391 because Honda is headquartered in this district, transacts business in this district, is subject to personal jurisdiction in this district, and therefore is deemed to be a citizen of this district. Additionally, Honda has advertised in this district and has received substantial revenue and profits from its sales and/or leases of Class Vehicles in this district; therefore, a substantial part of the events and/or omissions giving rise to the claims occurred, in part, within this district.
- 15. This Court has personal jurisdiction over Honda because it has conducted substantial business in this judicial district, is headquartered in this district, and intentionally and purposefully placed Class Vehicles into the stream of commerce

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

Santa Barbara, California 93101

within the districts of California, Florida, Maryland, New Jersey, Washington, and throughout the United States.

THE PARTIES

Plaintiff Victor Freeman

- 16. Plaintiff Victor Freeman is a citizen of the State of Florida and currently resides in Ponte Vedra Beach, Florida.
- 17. In October 2020, Plaintiff Freeman purchased a model year 2021 Honda Odyssey from Honda of the Avenues, an authorized Honda dealership located in Jacksonville, Florida.
- 18. Plaintiff Freeman purchased (and still owns) this vehicle, which is used for personal, family and/or household uses. His vehicle bears Vehicle Identification Number 5FNRL6H77MB008879.
- 19. Prior to purchasing his Class Vehicle, Plaintiff Freeman extensively discussed the features of the vehicle with Honda's sales representatives at Honda of the Avenues, test drove the vehicle, and also reviewed the vehicle's window sticker. None of these sources disclosed the Defect to Plaintiff Freeman.
- 20. On January 16, 2025, when his Odyssey had approximately 30,910 miles on the odometer, the power tailgate started to malfunction. While driving, he observed alerts on his dashboard, including a "vehicle stability assist (VSA) problem" and "antilock brake system problem." On January 17, 2025, Plaintiff Freeman brought his Class Vehicle to Honda of the Avenues, but because the dashboard alerts went away, Honda of the Avenues did not inspect the vehicle.
- 21. On January 22, 2025, the dashboard alerts came on again, and Plaintiff Freeman observed that the power tailgate would not open or close. He further observed that the power tailgate would not latch to the body of his Class Vehicle. In the interior of his Class Vehicle, Plaintiff Freeman noticed that the floor mats were wet.
- 22. On January 23, 2025, Plaintiff Freeman brought his Class Vehicle to Honda of the Avenues and requested warranty repairs. Employees at Honda of the

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

Santa Barbara, California 93101

- Plaintiff Freeman paid \$1,930.73 for the necessary repairs. 23.
- 24. On January 31, 2025, Plaintiff Freeman contacted Honda's corporate customer service line to file a claim for a refund/reimbursement. As of the date of this Complaint, Honda has not provided a response or resolution to Plaintiff Freeman's claim.
- 25. Plaintiff Freeman has suffered an ascertainable loss as a result of Defendants' omissions and/or misrepresentations associated with the Sealant Defect, including, but not limited to, out of pocket loss associated with the Sealant Defect and future attempted repairs and diminished value of his vehicle.
- 26. Neither Defendants, nor their agents, dealers or other representatives informed Plaintiff Freeman of the existence of the Sealant Defect prior to purchasing the Class Vehicle. Had Defendants disclosed the Sealant Defect prior to Plaintiff Freeman's purchase, Plaintiff Freeman would not have purchased the vehicle, or would have paid substantially less for it.

Plaintiff Kenneth Riker

- 27. Plaintiff Kenneth Riker is a citizen of the State of Washington and currently resides in Issaquah, Washington.
- 28. In October 2024, Plaintiff Riker purchased a certified pre-owned model year 2020 Honda Odyssey from AutoNation Honda of Renton, an authorized Honda dealership located in Renton, Washington.
- 29. Plaintiff Riker purchased (and still owns) this vehicle, which is used for personal, family and/or household uses. His vehicle bears Vehicle Identification Number 5FNRL6H73LB064865.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

- 30. Prior to purchasing his Class Vehicle, Plaintiff Riker extensively researched the vehicle online, including on Honda's website, CarFax, and Top Car Complaints. Additionally, he test drove the vehicle and discussed the features of the vehicle with Honda's sales representatives at AutoNation Honda of Renton.
- Approximately one week after purchase, when his Odyssey had 31. approximately 53,000 miles on the odometer, the power tailgate started to malfunction. Plaintiff Riker received a dashboard alert stating his Class Vehicle had a "power tailgate error." He was unable to open the power tailgate using the key fob or the button in the interior of the vehicle. Additionally, his Class Vehicle made beeping noises every ten seconds while the vehicle was turned on and running. On at least one occurrence, Plaintiff Riker received a dashboard alert stating that the tailgate was open when it was not. Following these incidents, the power tailgate in Plaintiff Riker's Class Vehicle became permanently stuck and would not unlock.
- In or around November 2024, Plaintiff Riker brought his vehicle to 32. AutoNation Honda of Renton, which diagnosed a power tailgate failure. According to the service record, AutoNation Honda of Renton found water inside the control module, and recommended replacement of the power tailgate control module. AutoNation Honda of Renton informed Plaintiff Riker that the necessary repairs would not be covered under warranty, Plaintiff Riker authorized the repair because he needed a safe and working vehicle.
- 33. Plaintiff Riker paid a \$100 deductible and the remainder of the repair was covered under his Class Vehicle's extended warranty.
 - 34. The below images depict Plaintiff Riker's damaged control module:


24 ///


/// 25

26 ///

27 ///

/// 28





SANTA BARBARA, CALIFORNIA 93101

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 201

Additionally, the first photo below depicts the power tailgate prior to repair 35. and the second photo shows the same tailgate after the purported repair:





3 4

5 6

7

8 9

10

11

12 13

Santa Barbara, California 93101 14

15 16

> 17 18

20

21

19

22

24

25

23

26 27

28

- 36. Less than two days after AutoNation Honda of Renton performed the necessary repairs, the power tailgate in Plaintiff Riker's Class Vehicle failed again.
- 37. Plaintiff Riker brought his vehicle back to AutoNation Honda of Renton, which informed him that they found a leak in the body of the vehicle which caused water intrusion into the tailgate and into the body of the vehicle. AutoNation Honda of Renton further informed Plaintiff Riker that the necessary repairs would not be covered under warranty. AutoNation Honda of Renton instructed Plaintiff Riker to take his vehicle to a third party body shop for repairs. Plaintiff Riker contacted three different body shops for repairs, and all of them refused to perform the necessary repairs. The body shops informed Plaintiff Riker that it would cost several thousands of dollars just to locate the leak, and even more to repair it. The body shops recommended that Plaintiff Riker perform the repair himself.
- 38. Plaintiff Riker has suffered an ascertainable loss as a result of Defendants' omissions and/or misrepresentations associated with the Sealant Defect, including, but not limited to, out of pocket loss associated with the Sealant Defect and future attempted repairs and diminished value of his vehicle.
- 39. Neither Defendants, nor their agents, dealers or other representatives informed Plaintiff Riker of the existence of the Sealant Defect prior to purchasing the Class Vehicle. Had Defendants disclosed the Sealant Defect prior to Plaintiff Riker's
- 40. purchase, Plaintiff Riker would not have purchased the vehicle, or would have paid substantially less for it.

Plaintiff Eugene Sullivan

- 41. Plaintiff Eugene Sullivan is a citizen of the State of New Jersey and currently resides in Pennington, New Jersey.
- In or around October 2020, Plaintiff Sullivan purchased a model year 2021 42. Honda Odyssey from Honda of Princeton, an authorized Honda dealership located in Princeton, New Jersey.

///

- 43. Plaintiff Sullivan purchased (and still owns) this vehicle, which is used for personal, family and/or household uses. His vehicle bears Vehicle Identification Number: 5FNRL6H70MB009856.
- 44. Prior to purchasing his Class Vehicle, Plaintiff Sullivan extensively researched the vehicle on Honda's websites. Additionally, he discussed the features of the vehicle with Honda's sales representatives at Honda of Princeton and reviewed the vehicle's window sticker.
- 45. On November 28, 2024, when his Odyssey had approximately 46,500 miles on the odometer, the power tailgate started to malfunction. The tailgate would not open when Plaintiff Sullivan pressed the button, nor when he attempted to manually open it. Plaintiff Sullivan had to load the back of his vehicle using the side door. When driving to Thanksgiving dinner, the dashboard of the Class Vehicle displayed an error code related to the power tailgate, and a beeping noise was emanating from the tailgate. The tailgate suddenly flew open, scaring Plaintiff Sullivan and his family. He immediately pulled over to the side of the road as fast as possible. Plaintiff Sullivan attempted to close the power tailgate, but it would not close or latch. Because the power tailgate would not close, exhaust fumes began entering the vehicle.
- 46. On November 29, 2024, Plaintiff Sullivan brought his Class Vehicle to Honda of Princeton. Employees at Honda of Princeton informed Plaintiff Sullivan that the latch had failed and that the necessary repairs would not be covered under warranty. Because Plaintiff Sullivan needed a safe and working vehicle, Plaintiff Sullivan authorized the latch repair. Later that day, Honda of Princeton called Plaintiff Sullivan and informed him that the latch repair had not fixed the issue with power tailgate and that they observed water in the control module, which was the cause of the failure. Because Honda of Princeton previously informed Plaintiff Sullivan that the necessary repairs would not be covered under warranty, Plaintiff Sullivan authorized the repair because he needed a safe and working vehicle.


1

- 3 4
- 5
- 6 7
- 8 9
- 10
- 11
- 12
- 13
- Santa Barbara, California 93101 14
- 15 16
- 17
- 18
- 19
- 20
- 21
- 22 23
- 24
- 25
- 27

26

28

- 47. Plaintiff Sullivan paid a total of \$1,167.93 for both the latch and control module unit repairs.
- When Plaintiff Sullivan retrieved his Class Vehicle from Honda of 48. Princeton after the repairs were performed, Plaintiff Sullivan noticed that employees of Honda of Princeton attempted to prevent water intrusion into the control module with a plastic bag. Plaintiff Sullivan took a picture of the purported "fix," which is included below:



49. Plaintiff Sullivan filed a complaint related to the Defect with the Transportation Security Administration ("TSA"). A TSA representative referred Plaintiff Sullivan to Honda. Honda attributed the Sealant Defect to normal water

2

3

4

5

6

7

8

9

10

11

18

19

20

21

22

23

24

25

26

27

28

12 33 WEST MISSION STREET, SUITE 201 SANTA BARBARA, CALIFORNIA 93101 13 14 15 16 17

- intrusion/damage and declined to reimburse Plaintiff Sullivan for his out-of-pocket expenses.
- 50. Plaintiff Sullivan has suffered an ascertainable loss as a result of Defendants' omissions and/or misrepresentations associated with the Sealant Defect, including, but not limited to, out of pocket loss associated with the Sealant Defect and future attempted repairs and diminished value of his vehicle.
- 51. Neither Defendants, nor their agents, dealers or other representatives informed Plaintiff Sullivan of the existence of the Sealant Defect prior to purchasing the Class Vehicle. Had Defendants disclosed the Sealant Defect prior to Plaintiff Sullivan's purchase, Plaintiff Sullivan would not have purchased the vehicle, or would have paid substantially less for it.

Plaintiff Santosh Ameti

- 52. Plaintiff Santosh Ameti is a citizen of the State of Washington and currently resides in Bellevue, Washington.
- 53. In or around December 2019, Plaintiff Ameti purchased a model year 2019 Honda Odyssey from Honda of Bellevue, an authorized Honda dealership located in Bellevue, Washington.
- 54. Plaintiff Ameti purchased (and still owns) this vehicle, which is used for personal, family and/or household uses. His vehicle bears Vehicle Identification Number: 5FNRL6H71KB091884.
- 55. Prior to purchasing his Class Vehicle, Plaintiff Ameti extensively discussed the features of the vehicle with Honda's sales representatives at Honda of Bellevue and reviewed the vehicle's window sticker.
- 56. In or around October 2024, when his Odyssey had approximately 23,000 miles on the odometer, the power tailgate started to malfunction. The tailgate would not open when Plaintiff Ameti pressed the button, nor when he attempted to manually open it. Additionally, the dashboard of the Class Vehicle displayed an error

code related to the power tailgate, and a beeping noise was emanating from the tailgate. Plaintiff Ameti further observed water inside the rear of the vehicle.

- 57. On November 4, 2024, Plaintiff Ameti brought his Class Vehicle to Honda of Bellevue. Employees at Honda of Bellevue informed Plaintiff Ameti that they found evidence of water intrusion on the inside of the control panel, observed the cargo area carpet was soaked with water, and that the circuit board and connectors had been corroded due to water intrusion.
- 58. Plaintiff Ameti took a picture of the damaged circuit board as a result of the Sealant Defect, which is included below:



6

10

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 201

27 28

- 59. Honda of Bellevue informed Plaintiff Ameti that the necessary repairs would not be covered under warranty. Because Plaintiff Ameti needed a safe and working vehicle, Plaintiff Ameti was forced to pay out of pocket for the repairs.
 - 60. Plaintiff Ameti paid a total of \$813.13 for the necessary repairs.
- 61. Plaintiff Ameti has suffered an ascertainable loss as a result of Defendants' omissions and/or misrepresentations associated with the Sealant Defect, including, but not limited to, out of pocket loss associated with the Sealant Defect and future attempted repairs and diminished value of his vehicle.
- Neither Defendants, nor their agents, dealers or other representatives 62. informed Plaintiff Ameti of the existence of the Sealant Defect prior to purchasing the Class Vehicle. Had Defendants disclosed the Sealant Defect prior to Plaintiff Ameti's purchase, Plaintiff Ameti would not have purchased the vehicle, or would have paid substantially less for it.

Plaintiff Shammara Hannah

- Plaintiff Shammara Hannah is a citizen of the State of Maryland and 63. currently resides in Owings Mills, Maryland.
- 64. In 2022, Plaintiff Hannah purchased a certified pre-owned model year 2019 Honda Odyssey from Honda of Owings Mills, an authorized Honda dealership located in Garrison, Maryland.
- 65. Plaintiff Hannah purchased (and still owns) this vehicle, which is used for personal, family and/or household uses. Her vehicle bears Vehicle Identification Number: 5FNRL6H76KB114995.
- 66. Prior to purchasing her Class Vehicle, Plaintiff Hannah extensively discussed the features of the vehicle with Honda's sales representatives at Honda of Bellevue and reviewed the vehicle's window sticker.
- 67. In or around May 2024, when her Odyssey had approximately 53,500 miles on the odometer, the power tailgate started to malfunction. The tailgate

2

3

4

5

6

7

8

9

10

23

24

25

26

27

28

would not open when Plaintiff Hannah pressed the button or the keyfob, nor when she
attempted to manually open it. Plaintiff Hannah contacted Honda of Owings Mills to
report the issue and request a repair. However, she was informed that they would no
provide her with a loaner vehicle, which was essential for her and her children. As a
result, Plaintiff Hannah had no choice but to seek repairs elsewhere.

- Plaintiff Hannah brought her vehicle to LMW Auto Repair, an auto repair 68. shop located in Randallstown, Maryland. LMW Auto Repair diagnosed a power tailgate failure. Plaintiff Hannah paid a total of \$1,690.62 for the necessary repairs.
- In February 2025, the power tailgate in her Class Vehicle again failed. 69. Plaintiff Hannah observed a "power liftgate failure" alert on the dashboard of her Class Vehicle. Plaintiff Hannah brought her vehicle back to LMW Auto Repair, which found water intrusion in the power liftgate control module unit.
- 70. As shown below, the white-translucent matter on the control module and case represents water damage. The images below depict Plaintiff Hannah's damaged control module:



NYE, STIRLING, HALE, MILLER & SWEET





FIRST AMENDED CLASS ACTION COMPLAINT

71.

water intrusion company at her expense.

LMW Auto Repair refused to repair the vehicle and recommended that

SANTA BARBARA, CALIFORNIA 93101

2 Plaintiff Hannah seek warranty repairs through a Honda dealership. Plaintiff Hannah contacted Honda of Owings Mills but has not received a response as of the date of this 3 Complaint. Plaintiff Hannah contacted Anderson Honda, an authorized Honda 4 5 dealership located in Cockeysville, Maryland. Anderson Honda refused to perform the 6 necessary repairs and instead instructed Plaintiff Hannah to seek repairs from a local

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

1

- Plaintiff Hannah contacted Leak Doctors, an auto leak specialist located in 72. Brooklandville, Maryland. Plaintiff Hannah paid a total of \$345 for the necessary repairs.
- 73. Plaintiff Hannah has suffered an ascertainable loss as a result of Defendants' omissions and/or misrepresentations associated with the Sealant Defect, including, but not limited to, out of pocket loss associated with the Sealant Defect and future attempted repairs and diminished value of her vehicle.
- 74. Neither Defendants, nor their agents, dealers or other representatives informed Plaintiff Hannah of the existence of the Sealant Defect prior to purchasing the Class Vehicle. Had Defendants disclosed the Sealant Defect prior to Plaintiff Hannah's purchase, Plaintiff Hannah would not have purchased the vehicle, or would have paid substantially less for it.

Plaintiff Julio Angulo

- Plaintiff Julio Angulo is a citizen of the State of California and currently 75. resides in Chula Vista, California.
- 76. In January 2019, Plaintiff Angulo purchased a certified pre-owned model year 2018 Honda Odyssey from Mossy Honda, an authorized Honda dealership located in Lemon Grove, California.
- 77. Plaintiff Angulo purchased (and still owns) this vehicle, which is used for personal, family and/or household uses. His vehicle bears Vehicle Identification Number: 5FNRL6H72JB063221.

4 5

6 7

8 9

10

11

12 13

SANTA BARBARA, CALIFORNIA 93101 14 15

16 17

19

18

20 21

22

23

24 25

26 27

28

- 78. Prior to purchasing his Class Vehicle, Plaintiff Angulo extensively discussed the features of the vehicle with Honda's sales representatives at Mossy Honda and reviewed the vehicle's window sticker.
- 79. On February 1, 2023, when his Odyssey had approximately 44,376 miles on the odometer, the power tailgate started to malfunction. The tailgate would not open when Plaintiff Angulo pressed the button, nor when he attempted to manually open it. Plaintiff Angulo brought his vehicle to Chula Vista Honda, an authorized Honda dealership located in Chula Vista, California. Chula Vista Honda diagnosed a power tailgate failure and informed Plaintiff Angulo that the necessary repairs would not be covered under warranty. Plaintiff Angulo declined the repairs and elected to repair the power tailgate himself.
- 80. Plaintiff Angulo purchased the necessary parts from Chula Vista Honda. Plaintiff Angulo paid approximately \$400 for the parts.
- Plaintiff Angulo has suffered an ascertainable loss as a result of 81. Defendants' omissions and/or misrepresentations associated with the Sealant Defect, including, but not limited to, out of pocket loss associated with the Sealant Defect and future attempted repairs and diminished value of his vehicle.
- 82. Neither Defendants, nor their agents, dealers or other representatives informed Plaintiff Angulo of the existence of the Sealant Defect prior to purchasing the Class Vehicle. Had Defendants disclosed the Sealant Defect prior to Plaintiff Angulo's purchase, Plaintiff Angulo would not have purchased the vehicle, or would have paid substantially less for it.

Defendants

83. Defendants American Honda and Honda Motor Company are automobile design, manufacturing, distribution, and/or servicing corporations doing business within the United States. Furthermore, Defendants design, manufacture, distribute, market, service, repair, sell and lease passenger vehicles, including the Class Vehicles.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

SANTA BARBARA, CALIFORNIA 93101

- 84. Defendant Honda Motor Company, Ltd., 2-1-1, Minami-Aoyama, Minatoku, Tokyo 107-8556, Japan is an automobile design, manufacturing, sale, leasing, distribution, and servicing corporation organized under the laws of Japan. Honda Motor Company is the parent corporation of American Honda.
- American Honda has its principal place of business at 1919 Torrance 85. Boulevard, Torrance, California 90501-2746.
- Upon information and belief, Defendant Honda Motor Company 86. communicates with Defendant American Honda concerning virtually all aspects of the Honda products it distributes within the United States.
- 87. Upon information and belief, the design, manufacture, distribution, service, repair, modification, installation and decisions regarding the body seam seals within the Class Vehicles were performed exclusively by Defendants.
- 88. Upon information and belief, the design, manufacture, distribution, service, repair, modification, installation and decisions regarding the body seam seals within the Class Vehicles were performed exclusively by Honda.
- Upon information and belief, Honda develops the owner's manuals, 89. warranty booklets and information included in maintenance recommendations and/or schedules for the Class Vehicles.
- 90. Defendants American Honda and Honda Motor Company engage in continuous and substantial business in California.

TOLLING OF STATUTES OF LIMITATION

- 91. Any applicable statute(s) of limitations has been tolled by Honda's knowing and active concealment and denial of the facts alleged herein. Plaintiffs and members of the Class could not have reasonably discovered the true, latent defective nature of the Sealant Defect until shortly before this class action litigation was commenced.
- 92. Honda was and remains under a continuing duty to disclose to Plaintiffs and members of the Class the true character, quality and nature of the Class Vehicles

2

3

4

5

6

7

8

9

10

11

12

23

24

25

26

27

28

and that they will require costly repairs and diminishes the resale value of the Class Vehicles. As a result of the active concealment by Honda, any and all applicable statutes of limitations otherwise applicable to the allegations herein have been tolled.

FACTUAL ALLEGATIONS

The Sealant Defect within the Class Vehicles.

The Class Vehicles, like many modern automobiles, feature a unibody 93. construction, which serves as the structural foundation of the vehicle. Unlike a bodyon-frame construction where the body sits atop the frame, in a unibody construction the body and frame are considered one unit, and typically incorporate the body, floorboards, and structural elements in one large structure. An exemplar image of a unibody construction is included below:



- During assembly, various panels and components are affixed to the frame, 94. such as the body panels, through mounting points within the frame.
- 95. A body seam is the joint or connection point within which body panels or components meet. Examples of seams throughout modern automobiles are where the doors meet the body of the car and where the roof connects to the side panels.

2

9

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 201

19

- 96. In order to fill in any gaps between the body frame and the various panels affixed to the frame, a sealant is applied. The sealant is applied to prevent water, dust, air, or other substances or particulates from entering the interior of the vehicle while it is being operated.
- 97. Most modern automobiles, including the Class Vehicles, utilize a polyurethane sealant. Polyurethane refers to a polymer that combines polyols (alcohols with multiple hydroxyl groups) with isocyanates to form a polymer. Polyurethane seals are often used in automotive applications because, in addition to preventing water infiltration, they also absorb vibrations and reduce noise on the interior of the vehicle. Polyurethane is also flexible, which allows for slight movements between the panels without compromising the seal.
- 98. The polyurethane seals on the Class Vehicles, however, suffer from one or more manufacturing and/or design defects that cause them to crack and fail and allow water to infiltrate the interior of the Class Vehicles.
- 99. Specifically, the polyurethane seals on the Class Vehicles fail due to a combination of manufacturing variability and inadequate surface preparation.
- 100. Manufacturing variability refers to inconsistencies in the application of the seal during the manufacturing process. Specifically, the seals are improperly cured. Curing is the process by which a sealant hardens and develops its final properties after application, and involves the chemical reaction between the components of the sealant. In the case of polyurethane sealing, it is the reaction between the polyols and isocyanates, which creates urethane linkages. Moisture-curing is often used, which exposes the seal to humidity to complete the curing process. As the seal cures, it is converted from a viscous liquid into a flexible, durable solid.
- 101. Properly curing a polyurethane seal is imperative to ensure that it performs effectively and does not prematurely fail.

///

///

1

4 5

7 8

6

9 10

11 12

Santa Barbara, California 93101 13 14

15 16 17

19

18

21

22

20

23 24

26

25

27 28

The Class Vehicles' body seam seals are defective because they are 102. improperly cured. Improper curing is a manufacturing defect whereby the curing process yields weak spots that are subject to premature failure.

- 103. The Class Vehicles' body seam seals are also defective due to inadequate surface preparation due to debris remaining on the seam through the manufacturing process. In order to form a seal, the body seam must be sufficiently clean and prepped before sealing. If debris remains from the manufacturing process, it will prevent the sealant from properly adhering to the body, causing the sealant to peel, lift, and/or crack.
- 104. Together, the improper curing of the sealant and the inadequate surface preparation cause the polyurethane body seam seals to crack and fail under normal and foreseeable use. When the Defect manifests, it allows water to infiltrate the body seam and into the interior of the vehicle.
- 105. In addition, due to the unibody construction, there is significant flexing in the area where the body seam seal is subject to premature failure, which the seal is unable to compensate for.
- 106. The seal most commonly fails at the top of the body seam on the driver's side near the back passenger window. Importantly, the tailgate control module also sits within the interior of the rear trunk panel, which is in close proximity to the failed seam seal. Once water infiltrates the body seam, it progresses through the panel of the vehicle until it reaches the tailgate control module.
- 107. The tailgate control module is an electronic component that is responsible for the operation of the tailgate, which includes opening it, closing it, and locking it. The module communicates with the Class Vehicles' other electrical components and sensors that detect whether it is open or closed, or whether obstructions are detected that would prevent the safe operation of the power tailgate.
- 108. When water comes into contact with the tailgate control module, it causes the module to malfunction in a variety of ways. First, water exposure can cause short circuits within the electrical components, leading to malfunctioning of the tailgate

control (e.g., a short circuit can cause the tailgate to improperly open or close without any input from the operator of the Class Vehicle). Second, water exposure can cause corrosion, which degrades the performance of the module over time, and eventually will cause the total failure of the module, meaning the power liftgate will be rendered entirely inoperable.

109. Once the Sealant Defect manifests, authorized Honda dealerships recommend the replacement of the tailgate control module. Because this does not remedy the root cause of the Sealant Defect, it is only a matter of time until the replacement tailgate control module comes into contact with water that infiltrates through the defective sealant and also experiences short circuits and corrosion, ultimately failing again shortly after replacement.

B. <u>Safety Issues Caused by the Sealant Defect</u>

- 110. The Sealant Defect and malfunctioning tailgate control module pose a number of serious, safety-related issues for operators of the Class Vehicles and those that share the road with them.
- 111. A short circuit can cause an electrical fire.² Once the fire starts in the control module, it can easily spread to the rest of the vehicle. Consumers have voiced their concerns about electrical fires in their complaints to NHTSA, which are reproduced below. *See* NHTSA IDs 11527986 & 11501226.
- 112. Water infiltration can also cause mold to grow. Because the Sealant Defect allows water to infiltrate the top of the body seam and flow down the driver's side body, and because the interior of the body is not exposed to the sun or other mechanisms that would allow the water to dry, mold growth is not only possible, but probable. The mold growth in the Class Vehicles caused by the Sealant Defect is particularly insidious because it is not visible to the driver or occupants of the Class Vehicles. Consumers

² <u>https://rytecelectric.com/blog/what-is-an-electrical-short-circuit/</u>;

https://earlybirdelectricians.com/blog/the-dangers-of-wet-electrical-wiring/ (both last visited February 28, 2025).

have likewise complained about mold growth to NHTSA. See NHTSA IDs 11608694, 11597496, & 11323163.

- 113. The short circuits and corrosion of the tailgate control module can also cause the battery to drain. Specifically, short circuits can cause excessive current draw, causing the battery to drain quickly even when the Class Vehicle is off because the tailgate control module stays energized, causing continuous power drain. Corrosion can also lead to poor electrical connections, causing the tailgate control module to draw more power than necessary, which also causes the battery to drain. Once the battery is drained, the occupants of the Class Vehicles are left stranded until the battery can be recharged. Consumers have complained about this to NHTSA too. *See* NHTSA IDs 11563377, 11475412 & 11473935.
- 114. The Sealant Defect also causes the tailgate control module to malfunction and abruptly open or close the power tailgate. Consumers have reported the power tailgate suddenly opening while driving, which happened to Plaintiffs. Other owners have reported that the tailgate abruptly closed while they were loading or unloading the trunk, causing them to be physically struck by the tailgate. *See* NHTSA IDs 11526594 and 11537560.
- 115. The Sealant Defect can also cause the body to rust from the inside. Rust compromises the structural integrity of the frame and makes it more susceptible to bending or breaking when placed under stress. In addition, rust can quickly spread to adjacent areas. Consumers have observed and reported rust caused by the Sealant Defect directly to NHTSA. *See* NHTSA IDs 11593412 & 11531122.

C. <u>Honda's Knowledge of the Sealant Defect</u>

116. Honda markets its vehicles as reliable when compared to the competition.³

///

³ See, e.g., https://automobiles.honda.com/awards (last visited February 28, 2025).

117. Automobiles must be able to withstand foreseeable usage conditions. A vehicle can suffer extensive damage and costly repairs from customary environmental and usage conditions when a vehicle suffers from a defect such as the Sealant Defect.

- 118. In many instances, consumers have incurred and will continue to incur expenses for repair of the body seam and tailgate control module despite the Sealant Defect having been contained in the Class Vehicles when manufactured by Honda.
- 119. Upon information and belief, Honda, through (1) its own records of customers' complaints, (2) dealership repair records, (3) records from the National Highway Traffic Safety Administration (NHTSA), (4) warranty and post-warranty claims, (5) internal pre-sale durability testing, and (6) other various sources, was well aware of the Sealant Defect but failed to notify customers of the nature and extent of the problems with Class Vehicles' body seam seals or to provide any adequate remedy.
- 120. Honda failed to adequately research, test and/or manufacture the body seam seals in the Class Vehicles before warranting, advertising, promoting, marketing, and selling the Class Vehicles as suitable and safe for use in an intended and/or reasonably foreseeable manner.
- 121. Honda is experienced in the manufacture of consumer vehicles. As an experienced manufacturer, Honda conducts tests, including pre-sale durability testing, on incoming components, including the body seams and seals, to verify that the parts are free from defects and align with Honda's specifications.
- 122. Honda's presale durability testing includes five metrics that allegedly "ensure high quality" by conducting "comprehensive quality assurance activities from the dual perspectives of planning and manufacturing." Honda admits that its "production departments implement manufacturing controls to keep variability within applicable standards based on drawings and develop production processes so that all

⁴ <u>https://global.honda/en/sustainability/cq_img/report/pdf/2018/Honda-SR-2018-en-065-078.pdf</u> (last visited February 28, 2025). The quotes in paragraphs 69-76 all refer to this webpage.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

workers can continue to achieve a consistent level of quality." Thus, Honda knew or should have known of the Sealant Defect through its comprehensive quality assurance activities and manufacturing controls.

- 123. First, Honda's "engineers utilize a database of measures and techniques previously used to prevent market quality issues and other information. They communicate closely with manufacturing departments during the initial development stage and put product function, performance and quality assurance initiatives in writing. These are shared to ensure efforts are coordinated with production departments' process assurance activities and to coordinate quality assurance initiatives."
- 124. Second, "Honda's production departments establish manufacturing control items and criteria for each part, process, and operation to prevent product quality issues." These controls are explicitly put in place to "prevent product quality issues" whereby Honda's engineers "use these manufacturing control items and criteria to verify manufacturing variability."
- 125. Third, for outsourced parts, Honda visits its suppliers' manufacturing facilities to conduct quality audits based on the "Three Reality Principle,' which emphasizes 'going to the actual place,' 'knowing the actual situation' and 'being realistic." Honda uses "[e]xperts in the development and production of individual parts visit manufacturing facilities and conduct audits of suppliers' quality systems and their implementation."
- 126. Fourth, and perhaps most importantly, Honda assures long-term reliability of its parts and vehicles through "rigorous durability testing." Honda states the following about this metric (emphasis added):

Honda subjects new and redesigned models to rigorous long-distance durability testing before beginning mass production to verify that there are no quality issues.

Honda also disassembles vehicles used in the test drives into every single part and verifies that there are no quality issues through a process consisting of several thousand checks. By accumulating data on the issues

8

9

1

2

3

4

11

12

10

13 14

Santa Barbara, California 93101 15 16

17 18

19

20

21 22

23 24

25

26

27

28

discovered through these test drives and detailed inspections as well as associated countermeasures, the Company is able to ensure a high level of quality and reliability.

- 127. Fifth, Honda developed and implemented the "Line End Tester," an inspection and diagnostic system, that is used "in shipping quality inspections of all electronic control systems, from switches and instruments to air conditioner, audio, engine and transmission operations."
- 128. Through these quality control metrics, Honda knew or should have known that the body seam seals in the Class Vehicles were defective.
 - 129. Lastly, as explained in Honda's Sustainability Report:

When Honda determines that an issue occurs with a product that requires market action, it quickly notifies government authorities in accordance with individual countries' regulations and contacts owners by means of direct mail from dealers or by telephone to provide information about how they can receive repairs free of charge. In addition to Honda's website, market action information is provided through the news media as necessary.

- 130. Despite such assurances and procedures, Honda has not contacted Class Members by direct mail or telephone to inform them how they can receive free repairs related to the Sealant Defect within the United States. Additionally, upon information and belief, Honda has also not provided associated information regarding the Sealant Defect on its website or through the news media.
- 131. Per the below, Honda also expressly warranted the Class Vehicles to be free from defects for a period of three years or 36,000 miles under the New Vehicle Limited Warranty.⁵ This warranty is applicable to the Sealant Defect; however, Honda has failed to correct the issue.

/// ///

⁵https://owners.honda.com/Documentum/Warranty/Handbooks/2019_Honda_Warranty_Base book_AWL07531_Petrol_Hybrid_PHEV__SIS.pdf, at 6 (last visited February 28, 2025).

NYE, STIRLING, HALE, MILLER & SWEET

3

1

2

4

5

7

8

9

10

1112

13

15 16

> 17 18

> > 19

20

21

2223

24

2526

27

28

Time and Mileage Period

This warranty begins on the date the vehicle is put into use in one of the following ways:

- The vehicle is delivered to the first purchaser by an authorized Honda automobile dealer.
- The vehicle is leased.
- The vehicle is used as a demonstrator or company vehicle.

Your vehicle is covered for 3 years or 36,000 miles, whichever comes first. Some parts may have separate coverage under other warranties described in this booklet.

Warranty Coverage

Honda will repair or replace any part that is defective in material or workmanship under normal use. See Operation and Maintenance of your Honda on page 36. All repairs/replacements made under this warranty are free of charge.

The replaced or repaired parts are covered only until this New Vehicle Limited Warranty expires.

This New Vehicle Limited Warranty Does Not Cover:

- Normal wear or deterioration of any part.
- · Cleaning and polishing.
- The adding of any fluids, unless they are needed as part of a warranty repair.
- Broken, chipped, or scratched window glass unless it is due to a defect in material or workmanship.
- Any item concerning your vehicle's general appearance that is not due to a defect in material or workmanship. Cosmetic flaws or minor damage to the body, paint, or other items may occur during manufacture or shipping of your vehicle. If you find any uncorrected flaws or damage on your new vehicle, notify the dealer as soon as possible after delivery.

New Vehicle Limited Warranty

- Expendable maintenance items (such as filters, or brake pads/ linings) when replaced due to normal wear or customer abuse.
- Tires are warranted by their manufacturers (see page 28 for more information).

Limited Warranty Coverage

- Original equipment batteries for key fobs and remotes are covered for the first 6 months of ownership.
- Original equipment wiper blade inserts are covered for the first 6 months of ownership.
- Wheel balancing and wheel alignment are covered for the first year or 12,000 miles, whichever comes first, unless required as part of a warranty repair.
- Air conditioner refrigerant is covered for the first 2 years or 24,000 miles, whichever comes first, unless required as part of a warranty repair.

Your Warranties in Detail

a

- 132. Buyers, lessees, and other owners of the affected Vehicles were without access to the information concealed by Honda as described herein, and therefore reasonably relied on Honda's representations and warranties regarding the quality, durability, and other material characteristics of the Vehicles. Had these buyers and lessees known of the defect and the potential harm, they would have taken steps to avoid that harm and/or would have paid less for the Vehicles than the amounts they actually paid, or would not have purchased the Vehicles.
- 133. Honda also issued a voluntary recall of certain MY2008-2009 Honda Odyssey vehicles in February of 2012 because "the tailgate of vehicles equipped with a power tailgate system may be prone to early life failures." There, Honda's recall involved free repairs of the power liftgate struts, which "help[ed] to raise and support the liftgate of vehicles." Honda admitted that the "manufacturing flaw" could result in

⁶ https://www.kbb.com/honda/odyssey/2009/recall/ (last visited February 28, 2025).

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

28

a leak in the pressurized struts and negatively impact their performance. This prior recall alerted Honda to the importance of a properly functioning power liftgate, and the detrimental impacts of manufacturing flaws on the liftgates.

D. Complaints by Other Class Members

- 134. Plaintiffs' experiences are by no means isolated or outlying occurrences. Indeed, the internet is replete with examples of blogs and other websites where consumers have complained of the exact same Sealant Defect within the Class Vehicles.
- 135. Class Vehicle owners have publicly complained to the United States government about the Sealant Defect in Class Vehicles since the vehicle has been released. The Office of Defects Investigation ("ODI") is an office within the National Highway Traffic Safety Administration ("NHTSA"). ODI conducts defect investigations and administers safety recalls to support NHTSA's mission to improve safety on the Nation's highways. ⁷ All automobile manufacturers routinely monitor and analyze NHTSA complaints because this information is used in determining if a recall should be issued. Indeed, automobile manufacturers are required by law to monitor NHTSA complaints and report any potential safety defects to the United States government. *See* TREAD Act, Pub. L. No. 106-414, 114 Stat. 1800 (2000). Thus, Defendants have knowledge of any and all NHTSA complaints.
- 136. The following is just a small sampling of the many complaints submitted to ODI by Class Vehicle owners. These publicly available complaints, filed as early as December of 2019, evidence Honda's prior knowledge of the Sealant Defect, the negative experiences encountered by Class Members, and the financial burden this place on them.
- 24 NHTSA ID Number: 11290516 Incident Date March 1, 2019
- 25 Complaint Date December 31, 2019 Consumer Location DAYTON, OH
- 26 Vehicle Identification Number 5FNRL6H74KB****
 Summary of Complaint

Summary of Complaint

⁷ See https://www.nhtsa.gov/resources-investigations-recalls (last visited February 28, 2025).

- 2019 HONDA ODYSSEY. CONSUMER WRITES IN REGARDS TO VARIOUS DEFECTS. *LD THE CONSUMER STATED ALL THE DOORS UNLOCK
- 2 INDEPENDENTLY. THE SLIDING DOORS, INCLUDING THE REAR HATCH, UNLOCK AND OPEN INDEPENDENTLY AND WHILE DRIVING. THE
- 3 VEHICLE WINDOWS AND SUNROOF OPEN FULLY INDEPENDENTLY, WHILE THE VEHICLE WAS LOCKED. *JS
 - NHTSA ID Number: 11323163
- 5 Incident Date February 13, 2018 Complaint Date May 4, 2020
- 6 Consumer Location HOUSTON, TX

Vehicle Identification Number 5FNRL6H78KB****

- 7 | Summary of Complaint
- REAR LIFT GATE WAS NOT PROPERLY MANUFACTURED AND WAS LEAKING WATER THAT COULD LEAD TO MOLD GROWTH. ISSUE WAS TAKEN INTO SERVICE 3 SEPARATE TIMES AND DIFFERENT LEAKS WERE
- 9 FOUND EACH TIME. HONDA CORPORATE PROVIDED NO ASSISTANCE OR SUPPORT FOR RESOLVING THIS ISSUE AND COULDN'T EVEN FIND
- 10 RECORDS OF THE COMPLAINT (I CALLED AND STARTED A CASE EACH TIME THANK GOODNESS I MAINTAIN RECORDS ON THIS). APPARENTLY,
- 11 HONDA CORPORATE HAS NO CONCERN ABOUT WATER LEAKS OR THE QUALITY OF THEIR MANUFACTURED PRODUCT ONCE IT IS SOLD TO A CONSUMER.
- 13 **NHTSA ID Number:** 11343124
- Incident Date February 2, 2020
 - Complaint Date August 4, 2020
 - Consumer Location DERWOOD, MD
 - 5 || Vehicle Identification Number 5FNRL6H56JB****
 - Summary of Complaint
 - WHILE VEHICLE IS STATIONARY, AFTER CLOSING THE REAR DOOR. THE DOOR LATCH WILL NOT ALWAYS HOLD THE REAR DOOR IN A FULLY CLOSED CONDITION, CAUSING A DOOR OPEN WARNING CONDITION. IT MAY TAKE SEVERAL ATTEMPTS TO FORCEFULLY SLAM THE REAR DOOR CLOSED BEFORE IT LOCKS CORRECTLY. THIS HAPPENS MULTIPLE TIMES EACH MONTH. ON VEHICLE WITHOUT AUTO CLOSING REAR DOOR OPTION.
- 20 | NHTSA ID Number: 11396844
- Incident Date December 30, 2020
- 21 Complaint Date February 18, 2021
- Consumer Location STOCKBRIDGE, GA
- 22 | Vehicle Identification Number 5FNRL6H70KB****
- || Summary of Complaint
- WATER KEEPS LEAKING IN THE TRUNK. EVERYTIME IT RAINS THERE IS A PUDDLE IN THE TRUNK. THIS HAS HAPPENED WELL OVER 15 TIMES AND
- 24 | AMERICAN HONDA HAS NOT ACKNOWLEDGED THIS BEING AS RECALL. THIS ISSUE HAS BEEN ALL OVER THE FORUM AND REDDIT AS WELL. I AM
- 25 NOT THE FIRST ONE THAT HAS FACED THIS ISSUE.
- 26 **NHTSA ID Number:** 11436110
- Incident Date May 26, 2021 Complaint Date October 8, 2021
- Consumer Location JACKSONVILLE, FL
- 28 | Vehicle Identification Number 5fnrl6h72jb****

Vehicle leaking water on backside and is causing electric issues. One of the issue is rear lift gate malfunctioning. The hatching opening on its own etc which is a safety risk. The dealer repaired this under warranty and they issue came back again almost four times so far. Now dealer is saying the issue is due to leaking water from top which they mentioned after vehicle went out of warranty and asking to contact body shop to identify the leak. The honda dealer not fixing the issue now. Please check if you received similiar

issue and help with me regarding the same.

5

6

7

9

10

11

12

13

15

16

4

NHTSA ID Number: 11455778 Incident Date March 23, 2018 Complaint Date March 8, 2022

Consumer Location BRENTWOOD, NH

Vehicle Identification Number 5FNRL6H76JB****

8 | Summary of Complaint

After leasing our car for less than 1 year - the power liftgate malfunctioned (which coincidentally there had been a recall in the past on our honda odyssey 2009 for appears to be the exact same issue.) It seems to be exactly the same thing happening again with the 2018 model we have now. So that the trunk won't open by itself. So for the past few years we had too manually lift the trunk and it's extremely heavy to lift and slow and can bang you in the head because it does not lift very high. If this wasn't bad enough a month ago the electrical power/fuse to even accomplish what I just explained electrically shorted for no reasonable explanation. So that my husband has to quite literally climb through the two rows of seats take the plastic off permanently on the manual/nonelectric trunk release from the inside of the car in order to get our trunk door to open at all. The outside of the car electrical button has no electricity running in it at all. This is terrible for a family of 5 children. There haven't been any recalls on this and I'm sure it'll be quite expensive to replace. Please look into this issue for us please. Thank you kindly. Please see below the recall in 2009 that should also be for the 2018 model as well. HONDA IS RECALLING CERTAIN MODEL YEAR 2008-2009 ODYSSEY VEHICLES, THE GAS-FILLED STRUTS THAT HELP TO RAISE AND SUPPORT THE LIFTGATE OF VEHICLES EQUIPPED WITH A POWER LIFTGATE SYSTEM MAY BE PRONE TO EARLY LIFE FAILURES DUE TO A MANUFACTURING FLAW. THE FLAW CAN RESULT IN A LEAK OF THE PRESSURIZED GAS, LEADING TO REDUCED STRUT PERFORMANCE.

17 18

19

20

22

23

24

25

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

NHTSA ID Number: 11459108 Incident Date March 20, 2022

Complaint Date March 31, 2022 Consumer Location RACINE, WI

21 Vehicle Identification Number 5FNRL6H2XLB****

Summary of Complaint

The contact owns a 2020 Honda Odyssey. The contact stated while driving at an undisclosed speed, the warning message "Lift Gate Open" illuminated. The vehicle was taken to the local dealer, where it was diagnosed that the lift gate was fractured. The vehicle was repaired; however, the failure recurred. The vehicle was taken to the same local dealer, where it was diagnosed that the striker plate needed to be replaced. The vehicle was repaired; however, the failure persisted. The vehicle was taken back to the local dealer but was not diagnosed or repaired. The manufacturer was notified of the failure but provided no assistance. The failure mileage was approximately 13,000.

26

27

NHTSA ID Number: 11473935 Incident Date February 1, 2022 Complaint Date July 14, 2022

28 | Consumer Location ANDREWS, SC

Vehicle Identification Number 5FNRL6H77JB**** 1 **Summary of Complaint**

The component that is giving me issues is the power liftgate. As I have been driving down the road, it has unlocked and opened even at a stoplight. And would go up and 3

down up and down until finally it runs the battery completely dead. I have taken it to Honda. They did not know what's causing it. I am taking it now to another service

dealer. to see if he can fix it. I'm in hopes that he can do something. But upon reviewing other complaints online, this has been an issue for other people. That could cause a lot 4

of safety issues for anyone around the vehicle or driving the vehicle. 5

- NHTSA ID Number: 11474577 6
- **Incident Date** January 18, 2019 **Complaint Date** July 18, 2022 7

Consumer Location SILVER SPRING, MD Vehicle Identification Number 5FNRL6H98JB****

8 **Summary of Complaint**

- The automatic tail gate hatch closes when its fully open. It will close while under it and 9 bumps your head if you're not careful. I have bumped my head a few times. Nothing serious enough to see a doctor but it happens 95% of the time the gate is opened. I 10 reported this to Honda dealer where I purchased the vehicle over two years ago before 11 COVID but it doesn't seem to concern them.
 - NHTSA ID Number: 11475412 **Incident Date** June 1, 2022 Complaint Date July 22, 2022

Consumer Location WARRIORS MARK, PA

Vehicle Identification Number 5FNRL6H79JB****

Summary of Complaint

Vehicle keeps turning on accessory mode uncommanded. Resulting in draining battery. Battery is then recharged and process starts over again. Took vehicle to Honda dealership for diagnosis. Dealership diagnosed tailgate control module. Disconnected all connections to that module and problem persists. Constant discharge and recharge of battery presents a fire hazard. A automotive/mechanical engineer evaluated the problem, suggested it was the body control module and highly recommended I not park my vehicle in my attached garage until the problem is resolved.

- NHTSA ID Number: 11478984 19 **Incident Date** August 12, 2022
- Complaint Date August 12, 2022 20

Consumer Location BROWNSBURG, IN

Vehicle Identification Number 5FNRL6H73JB**** 21

Summary of Complaint

- It is very common for the vehicle model to experience water intrusion toward the back 22 lift gate because of rain. This can cause electric problems with the vehicle that can result in property damage or death. Airbags may not deploy due to water damage as well. 23 These vehicles should be recalled as soon as possible. Most owner are not aware of this
- 24 issue because they park vans in a garage. Please investigate this matter and issue a recall
- NHTSA ID Number: 11497586 25 **Incident Date** November 15, 2022

Complaint Date December 15, 2022 26

Consumer Location PORT ORANGE, FL

Vehicle Identification Number 5FNRL6H92LB**** 27

Summary of Complaint 28

NYE, STIRLING, HALE, MILLER & SWEET 33 WEST MISSION STREET, SUITE 20

12

13

14

15

16

17

18

3

6

8

9

10

11

12

13

14

16

17

18

19

23

24

25

26

27

28

The contact owns a 2020 Honda Odyssey. The contact stated that the vehicle was leaking water from the roof seam near the driver's side rear of the vehicle. The leak caused water to form a puddle in the trunk tray compartment of the vehicle. The contact 2 had taken the vehicle to the dealer who resealed the roof seam. The manufacturer was made aware of the failure. The approximate failure mileage was 23,900.

NHTSA ID Number: 11501226 4 Incident Date November 23, 2022 Complaint Date January 11, 2023 5

Consumer Location FRIENDSWOOD, TX

Vehicle Identification Number 5FNRL6H72JB****

Summary of Complaint 7

GOODMORNING, I bought my car honda Odyssey 2018 model, on August 20th, 2018, from Honda of Clearlake, in League City, TX, the day they opened new location, this car has been giving us trouble since then, when under warranty the sunroof motor became faulty. I agree that they repaired it but took more than a week to get repaired. The car has less than 30000 miles now, last year November when I was driving car started showing up multiple warning lights, and tail gate not closing and locking and took the car dealer service center and without proper multi point inspection they ruled out its poor battery and changed it. Within a week again the same problem started appearing, took the car to dealer service center and took almost more than week to do inspection and stated that, there is a faulty weld and leak on back tail gate hinges in car and water is seeping into electrical system which is on driver side rear in between plastic trim and main body, this caused a short circuit and multiple warning lights turning on. electrical system and carpets were damaged, and they recommended to change whole harness and electrical components which will be more than \$6000.00 After a week they stated that it has a faulty caulk on roof were water seeping through, Honda of clear lake service advisor [XXX] agreed that he have come across multiple cars (3 or 4) in same dealer ship with same problems. nobody knows how many dealers service centers had same problem. This is clearly manufacturing defect and Honda corporate don't want to make this issue a recall. they agreed to replace components, but we have to pay the labor which we agreed, but it's been more than a month which they can't repair and give back our car. now I think this leak issue and the issue, I mentioned earlier (faulty sunroof motor) is somehow related. I would request you to probe an enquiry into this issue which, can be an electrical and fire hazard and rule out to be a recall from Honda side. Thanking you INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6).

NHTSA ID Number: 11511139 20 **Incident Date** January 18, 2023 **Complaint Date** March 10, 2023 21

Consumer Location Unknown

Vehicle Identification Number 5FNRL6H79LB**** 22

Summary of Complaint

On 18 January 2023 the tailgate on our 2020 Odyssey refused to open. Neither the inside switch nor the outside switch does anything. I crawled in the back and checked the fuses and both are good. I also discovered that the emergency tailgate release did not function. Took it to the dealer, Greenway Honda in Florence, Alabama, an hour from home, and they weren't able to find the fault with a cursory check and a reboot of whatever computer system is applicable. They said they need to keep it for at least a half day and "really tear into it." But we could not leave the vehicle at that time, having no transportation home. Eventual diagnosis determined the tailgate control module, the tailgate closure motor, and the tailgate latch had all failed. Parts were on backorder and no estimate on availability. After I contacted Honda corporate the parts suddenly became available at the dealership within a few days. Repairs were effected on 27

10

11

12

13

14

15

16

17

28

- February at Greenway Honda, Florence, Alabama. We were without the full use of our 1 vehicle for approximately six weeks. Occupants could become trapped in the vehicle if
- the front doors were disabled in a collision and electrical power was lost, rendering the sliding doors and the tailgate inoperative. The emergency release lever also would not function and this could trap occupants completely. Examination of the tailgate
- 3 electronic control module shows water infiltration which conceivably shorted the
- closure motor and jammed the latch, making it impossible to open the tailgate. Photos 4 of the failed electronic module were provided to the dealership and to Honda corporate.
- The failed parts are in my possession and are available for inspection. 5
- NHTSA ID Number: 11514170 6
- Incident Date March 23, 2023 Complaint Date March 28, 2023 7

Consumer Location PORTSMOUTH, NH

Vehicle Identification Number 5FNRL6H7XJB**** 8

Summary of Complaint

- While driving multiple system failure- warning lights then failure of: blind spot alert, lane departure, back up camera, wipers, tailgate function. When able to stop, power locks did not function. Inability to access rear of car via sliding doors would pose serious risk if accident occurred due to system failure. Prior to all systems alert, tailgate warning light had been intermittently appearing for a few days. Dealer service center noted water leak from unsealed section between window and frame in back driver side panel that corroded body console module.
- NHTSA ID Number: 11516508 **Incident Date** April 11, 2023 Complaint Date April 11, 2023 **Consumer Location** Unknown
- Vehicle Identification Number 5FNRL6H79KB****

Summary of Complaint

The rear power lift gage has stopped working due to leaking in the rear of the van. Per online threads, this is a common issue and should be a recall as so many issues have happened to other with this same problem.

- NHTSA ID Number: 11524076 18 **Incident Date** May 26, 2023
- Complaint Date May 26, 2023 19 Consumer Location Unknown
- **Vehicle Identification Number** 5FNRL6H7XJB**** 20

Summary of Complaint

- I have 2018 Odyssey EXL . on instrument display got message "Power Tailgate Issue" 21 The tailgate can not open either by control button or manually. I have already had this
- issue 2 times. I sent it to dealer and been told the power tailgate control module was 22 intruded by water. I replaced the control module, and after several months, the issue recovered. The power failgate can not open and close will cause my trip in danger. I 23
- hope the honda can fix this issue for the customers free.

24 NHTSA ID Number: 11526594

- **Incident Date** June 1, 2023 25 Complaint Date June 12, 2023
- **Consumer Location** Unknown 26
 - **Vehicle Identification Number** 5FNRL6H78MB****
- **Summary of Complaint** 27

6

7

8

9

10

14

15

19

20

21

22

23

26

27

28

The rear lift gate will be open and then all the sudden decide it needs to be shut. Beeps 1 really load and then come down hard and fast with no real time to recognize what is happening and get out of the way. It hurts and doesn't stop when it hits a person 2

NHTSA ID Number: 11527986 3 **Incident Date** August 1, 2022

Complaint Date June 20, 2023 4 Consumer Location Unknown

Vehicle Identification Number 5FNRL6H72JB****

Summary of Complaint

Rear hatch on our Odyssey EX-L started giving a "Power Tailgate Problem", and it would not open at all except by mechanically releasing the hatch from the emergency access panel. I replaced the rear hatch control module and the hatch could now again be opened from the outside as normal, but the power tailgate still did not function up and down, and requires manual lifting open and pushing closed. Upon inspection, the removed/malfunctioning control module appears to have failed due to water infiltration, meaning water has entered the inside of the vehicle and then shorted electrical components, potentially creating a fire hazard.

NHTSA ID Number: 11529349

11 **Incident Date** April 1, 2022 Complaint Date June 28, 2023

Consumer Location Unknown

Vehicle Identification Number 5FNRL6H74JB****

Summary of Complaint

Vehicle was taken into Honda dealer due to trunk not opening and closing properly & receiving "Power Tailgate Failure" warning and rear entertainment system not working. After many hours, I was told the power tailgate control unit and floor wire harness would need replaced due to corosion from water damage ??? This was at 42,653 miles!! They couldn't explain how the damage could have happened and Honda refused to do anything about fixing it.

NHTSA ID Number: 11531122 **Incident Date** June 22, 2023 Complaint Date July 9, 2023 Consumer Location Unknown

Vehicle Identification Number 5FNRL6H77JB****

Summary of Complaint

Water leaking in from roof or driver side windows into rear electronics at the fuse box and the tailgate control module. When control module was removed there was gross evidence of water saturation in the control module and multiple areas of corrosion, rust and fouling of electrical components causing battery to drain dead.

NHTSA ID Number: 11535640 Incident Date July 30, 2023 Complaint Date July 31, 2023

24 Consumer Location ORLANDO, FL

Vehicle Identification Number 5FNRL6H72JB****

Summary of Complaint 25

> After rainfall water is leaking into the rear fuse box compartment located behind the 3rd row seats and causing the tailgate control module and other parts to fail. The tailgate does not have any power and cannot be opened or closed with the fob or the push buttons located in the tailgate or in the dashboard area. The tailgate cannot be locked as the latch does not engage and it can be very risky to drive the vehicle as the tailgate might come

water is leaking into the fuse compartment and causing this hazardous situation.

3

6

7

1

Incident Date August 9, 2023 Complaint Date August 9, 2023

Consumer Location SUMMERVILLE, SC 4

Vehicle Identification Number 5FNRL6H72LB****

Summary of Complaint 5

1) The back hatch will randomly close. The first time it happened I didn't know what was going on and it hit me in the head. Today my kids were there and it almost hit them but I pushed them out of the way because I knew what was happening as it makes a certain noise first. 2) It stalls out randomly at red lights. 3) the doors won't open or close at times. 4) the dvd player gets so hot it almost burns you and the dvd player won't work. When I contact the dealer they say they can't do anything since it happens randomly and it if doesn't happen when it's at the dealership they don't know what to do so they don't even make an appointment. Two years ago we complained that the door didn't have a sensor because it shut my two year olds hand in the door. Honda acted like we were crazy. Then it became a recall and they 'fixed' them. But now they won't open or close.

open while driving. There might be some opening on the roof of the vehicle from where

11

10

13

14

15

NHTSA ID Number: 11539546 12

Incident Date August 1, 2023

Complaint Date August 19, 2023 Consumer Location NEW PORT RICHEY, FL

Vehicle Identification Number 5FNRL6H76KB****

Summary of Complaint

Power lift gate control module has shorted out due to water leak somewhere on my van. Board has visible water damage. Tailgate won't open or shut at all. Has to be done manually from inside the vehicle through trim opening on rear tailgate.

16 17 18

19

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

NHTSA ID Number: 11539871 **Incident Date** August 16, 2023 **Complaint Date** August 21, 2023 **Consumer Location MIAMI, FL**

Vehicle Identification Number 5FNRL6H72KB****

Summary of Complaint

The contact owns a 2019 Honda Odyssey. The contact stated that a message indicating 20 the power liftgate failure was displayed, and 2-3 days later, the power liftgate failed to open as needed. The vehicle was taken to the dealer, where it was diagnosed that water 21 intrusion in the power liftgate control module had caused the liftgate to fail to operate as designed. The vehicle was not repaired. The manufacturer was not notified of the 22 failure. The failure mileage was approximately 32,700.

23

27

28

NHTSA ID Number: 11542006

24 **Incident Date** August 31, 2023

Complaint Date September 1, 2023 Consumer Location EVERETT, WA 25

Vehicle Identification Number 5FNRL6H75JB****

Summary of Complaint 26

While the van was in motion, the power tailgate unlocked and opened on its own. The dashboard displayed tailgate open warning message. I slowed down and the lock reengaged to to close the tailgate. It happened again later that evening. Fortunately, I was within city limits, driving about 40 mph.

5

6

7

10

11

12

13

14

16

17

18

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

NHTSA ID Number: 11543594 **Incident Date** January 18, 2023 2

Complaint Date September 9, 2023 **Consumer Location** PLEASANT HILL, IA

Vehicle Identification Number 5FNRL6H7XJB****

Summary of Complaint 4

The power tailgate on my 2018 Honda Odyssey EX-L started opening and closing on its own, seemingly at random. The latch would not cinch and the gauge cluster reported an opening attempt while driving on the highway. This failure cascaded and ended up bringing every device on the B-CAN network down, including the instrument cluster, heated seats, power sliding doors, ADAS systems including FCW/LDW/LKA and various telltales and buttons on the dash. Upon disassembly of the interior to expose the affected controllers, I discovered that the power tailgate controller was full of water. There was enough water in it to cause arcing of the power and CAN terminals. I traced the ingress path upwards and discovered a crack in the seam sealer on the roof, underneath the left roof rack rail at the very rear of the vehicle. Water enters under the roof rail, drips down the door hinge, then drips down the body to the cup holder and directly into the controller. To remediate I had to replace the damaged controller and apply seam sealer underneath the roof rail at a cost of approximately \$200. I called the local dealer to attempt to report this to Honda but was unable to find the appropriate person. Over a dozen people have reported this issue online and there are pictures of the issue. I posted pictures to one of the links referenced below and have additional pictures. I believe this is a manufacturing defect and not caused by age or use of the vehicle and there is strong evidence it affects a lot of people. The issue will be particularly prevalent when the vehicle is parked outside on a downward incline. I work in a related industry on embedded devices that must meet functional safety standards, and I believe an issue like this would lead to a mandatory safety recall. [XXX] [XXX] INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5

NHTSA ID Number: 11544922 **Incident Date** August 26, 2023

Complaint Date September 16, 2023

Consumer Location BELLEVUE, WA

Vehicle Identification Number 5FNRL6H73KB****

19 Summary of Complaint

U.S.C. 552(B)(6)

The trunk lift gate can suddenly fail and slam down quickly, being a safety hazard. When the trunk opens, it will move up and down a few times, then it will beep three times and slam shut. It consistently happens when parked on an incline.

21

20

NHTSA ID Number: 11545031 22

Incident Date August 15, 2023 Complaint Date September 17, 2023 23

Consumer Location FORT LAUDERDALE, FL

Vehicle Identification Number 5FNRL6H75KB**** 24

Summary of Complaint

rear tailgate seal failure 2019 honda odyssey allowing water intrusion and corrosion of 25 lift gate control module, per ft lauderdale honda dealer. Not a safety issue but a design 26 defect per other honda owners.

NHTSA ID Number: 11545160 27 **Incident Date** September 8, 2023 28

Complaint Date September 18, 2023

14

15

16

17

18

19

28

1 || Consumer Location HENDERSON, NV

Vehicle Identification Number 5FNRL6H81JB****

2 | Summary of Complaint

The contact owns a 2018 Honda Odyssey. The contact stated that upon opening the electronic tailgate and entering the trunk of the vehicle, an alert sounded, indicating that the tailgate was closing. After closing the tailgate, the tailgate suddenly jerked open, striking the contact. No warning lights were illuminated. The vehicle was taken to the

- striking the contact. No warning lights were illuminated. The vehicle was taken to the dealer, who was unable to duplicate the failure. The vehicle was then taken to an independent mechanic, who was also unable to duplicate the failure. The vehicle was
- independent mechanic, who was also unable to duplicate the failure. The vehicle was not repaired. The manufacturer was notified of the failure but was unable to assist. The

6 | failure mileage was 172,000.

- 7 NHTSA ID Number: 11548844 Incident Date October 7, 2023
- 8 Complaint Date October 7, 2023 Consumer Location Unknown

9 Vehicle Identification Number 5FNRL6H98JB****

Summary of Complaint

- Every time when it rains, the power tail gate fails showing beeping noise from the rear and on the screen and unable to lock the doors. Had to replace the power tail module couple of times so far and still problem persists. The Honda dealership mentioned there was a leak, repaired and replaced the module, inspite of the fix priblem still persists when it rains
 - NHTSA ID Number: 11555697 Incident Date October 30, 2023
 - Complaint Date November 17, 2023 Consumer Location LOVELAND, OH
 - Vehicle Identification Number 5FNRL6H82KB****

Summary of Complaint

The motor that raises and lowers the rear liftgate failed and has been repaired already at a Honda Dealership. The van is not even 5 years old yet and the motor failing caused the lift gate to droop after opening causing my wife and I to bang our heads on it if we weren't watching for it. The more important safety concern is if the liftgate lowers to a certain point, the motor causes it to bounce up and down slightly and then automatically close. My concern for the safety of my young children made me get it repaired promptly. The honda dealership did confirm that the motor failed and it caused strain on the right strut as well need it to be replaced as well. There were no warning lights on dash. This

20 is a youtube link to someone else with the same van and year with the same problem. This is what my van was doing. [XXX] INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

22 NHTSA ID Number: 11557345 Incident Date October 27, 2023

23 Complaint Date November 28, 2023

Consumer Location ROCKLEDGE, FL

24 | Vehicle Identification Number 5FNRL6H73JB****

Summary of Complaint

Water intrusion on the driver side rear panel has caused the power tailgate command module to short out twice now.

NHTSA ID Number: 11557923 Incident Date November 3, 2023

Complaint Date December 1, 2023

Consumer Location POUGHKEEPSIE, NY

Tailgate controller issue. 2018 Honda Odyssey: A day after a day of rain, we went out shopping and stopped at a store. Getting out, we saw "Tailgate Controller Problem" message appear on the dashboard. I tried to open/close the tailgate but it just kept latching and unlatching. I was finally able to get it to remain closed by pushing on the tailgate. After heading to another store, saw a "high-beam problem" message, and another message, so we went home. At night, I noticed the interior ceiling lights going on and off. I went to start the van, and my key fob would not unlock the door. I used the emergency key in the fob and tried opening the drivers door...after 45 seconds of turning left and turning right, the windows rolled down about an inch, then the door unlocked. I started the van and moved it up in the driveway and turned it off, and checked a couple of times all night to see if the lights came back on. The next morning, I had to charge the battery because it was at 3Vs. I drove the van to make sure the alternator was working, and then saw messages: blinking "R" for reverse blinking "D" and no turn signals, and messages appeared: "Transmission Problem". "Keyless Start System Problem", "Blind Spot Info System Problem". We dropped the van off at the dealer and it would not lock with the fob, and the center dashboard console (with the navigation menu)remained on with the engine off and door closed. Dealer ordered a Tailgate Controller. When we asked the person at the desk, what the issue was..."moisture got in". I told him there is a discussion on the internet about a (design) leak in the roof causing this issue. He said, the controller is in the tailgate not in the van. But I know its on the side panel. This situation is very dangerous because a week before we had traveled with the van, out of state, on the interstate, trying to get people to airports and if these messages had appeared then, we would have had a very harrowing experience. A message is still seen

NHTSA ID Number: 11558852 **Incident Date** December 2, 2023 Complaint Date December 6, 2023 **Consumer Location FRISCO, TX**

Vehicle Identification Number 5FNRL6H71KB****

Summary of Complaint I am writing to express my deep concern regarding the significant reliability issues I have encountered with my 2019 Honda Odyssey. Unfortunately, these issues have led to inconveniences, unexpected expenses, and a reevaluation of my trust in the vehicle's long-term dependability. During the warranty period, the vehicle suffered from water infiltration in the trunk, resulting in flooding. Addressing this problem required multiple interventions by the dealership. Post-warranty, an electrical/electronic component related to the liftgate module malfunctioned, leading to an unforeseen repair that cost upwards of \$800+. Subsequently, the vehicle experienced recurring starting problems, necessitating jump-starts on multiple occasions. Most recently, a complete failure to start occurred, requiring towing to the dealership, which unfortunately happened while away from home. Extensive diagnostics revealed the necessity to reprogram the BCM (Body Control Module) to resolve the issue. The repetitive and varied nature of these issues, especially for a four-year-old vehicle, raises concerns about the reliability and quality standards associated with the Honda Odyssey. These recurring inconveniences and unexpected expenses have compelled me to reconsider recommending this vehicle to friends and family. Of particular concern is the possibility of experiencing a breakdown in remote areas during extended trips. The prospect of being stranded with my family in such situations is troubling and potentially unsafe. Urgent attention to resolving these issues is crucial to avoid any untoward incidents for myself or other Odyssey owners. While I have raised my concerns with Honda, I am also contemplating sharing this experience with the NHTSA. The uncertainty surrounding potential future issues while driving has led me to consider selling this vehicle. I believe it's essential to

1

3

4

5

6

7

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

10

11

12

13

14

16

17

18

document these concerns for the safety and awareness of others who might face similar 1 situations.

2 NHTSA ID Number: 11560655

Incident Date November 28, 2023 3

December 18, 2023

Consumer Location TACOMA, WA 4

Vehicle Identification Number 5FNRL6H70KB****

Summary of Complaint 5

My power tailgate control unit is fried due to a leak in rear driver side.

NHTSA ID Number: 11561397 Incident Date December 11, 2023

Complaint Date December 21, 2023

Consumer Location OVIEDO, FL

Vehicle Identification Number 5FNRL6H89MB****

9 **Summary of Complaint**

All of the safety system and efficiency systems had failures which made us take to our local Honda dealership for evaluation. After the first visit we were told that they could not find the problem, although they saw all of the error messages. The error messages appeared again 3 days later so we took it back to our local Honda dealership. This time one of the service reps had seen that problem before and said it probably was due to water entering the rear trunk circuit board controller and shorting out the connections. This was confirmed by a service tech during the 2nd evaluation. After research this is apparently a common issue. We had to pay approximately \$700 to fix the situation because Honda does not have this issue as a recall. We believe this is a clear design error that allows water to enter the circuit board housing. This created a dangerous situation as the head lamps as well as the driver safety features and direction signals intermittenly worked due to the shorted out circuit board.

NHTSA ID Number: 11563196 **Incident Date** December 26, 2023

Complaint Date January 2, 2024 Consumer Location GERMANTOWN, MD

Vehicle Identification Number 5FNRL6H77KB****

Summary of Complaint

Rear lift gate ceased operating, unlocking or opening. Later received errors on dash for 19 blind spot malfunction and transmission error. Dealer says it is an issue with water leaking into the rear chassis getting into the exposed electronics. 20

NHTSA ID Number: 11563419 21

Incident Date December 27, 2023 Complaint Date January 3, 2024

22 **Consumer Location** Unknown

Vehicle Identification Number 5FNRL6H71LB**** 23

Summary of Complaint

24 In my area, there has been lots of heavy rain. There was a water leak on the interior rear driver side, causing the tailgate control module (TCM) to fail part # 74970-THR-A12 25

The tailgate trunk or 5th door is not working, will not open, will not activate. I took my 2020 honda odyssey my local dealership but no help. Many vans from Honda, years

2018-2021 are having this very same issue. Please help Me resolved this matter. Honda 26 should have a recall on this and replace at no charge.

27 NHTSA ID Number: 11563377 **Incident Date** December 27, 2023 28

9

13

14

15

16

17

18

19

20

21

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

Vehicle Identification Number 5FNRL6H75KB****

Summary of Complaint

Power tailgate problem repeatedly flashed on dashboard but would disappear before it 3 was legible and the car was beeping while driving. We stopped and tried to see what the problem was but it wasn't until we finally arrived home that it finally showed the 4 full error on the screen. Apparently this drained the battery as well and we had to call AAA the following day to start the vehicle. They tested the battery which was only 2 5

years old (OEM battery died after only 2 years) and said it was fine. Drive around for 40 minutes and the next day it was dead again. Had it towed to the dealer who after much discussion agreed to replace the battery even though I read online about people having issues with water leaking onto the power tailgate module. The dealer told Me

7 they had to replace the battery instead and the next day called to say that I was right, the battery replacement didn't solve it. And when they looked at the power tail get module it was indeed corroded from moisture. But they wanted an additional \$500 so

they could subcontract to an "expert" who could seal that leak. I told them to only replace the module and asked why a recall hadn't been issued. They said this was

beyond their pay grade. I told them I'll find a way to seal it myself. 10

NHTSA ID Number: 11563361 11

Incident Date December 28, 2023 **Complaint Date** January 3, 2024 12

Consumer Location BOYCE, LA

Vehicle Identification Number 5FNRL6H7XJB****

Summary of Complaint

Power Tailgate failure, from water leaking into the vehicle. The power tailgate would open and close on its own, even when driving down the road. This is a SERIOUS safety issue if you have children in the vehicle. First sign of failure was a message of tailgate problem on the information center of the dash. That is when the intermittent opening and closing began, as well as battery going dead. Took to Honda to be serviced(Walker Honda in Alexandria, Louisiana). Was informed that water did indeed leak into the van from someplace, they did not know from where. Was told van needed a new battery as well as a module replacement for the power tailgate and a Water test to see where the water was leaking in. Total cost of around \$1600 Was then informed that the entire wiring harness might also need to be replaced because water corroded or damaged the contacts on the harness that affect MANY other parts of the van, including some safety systems. That was an estimated cost of \$7000 but was told the technician could possibly just clean off the wiring harness contacts and try to drive it that way and see if it fixes the problem. Van has little over 130,000 miles on it and Power Tailgate is rarely used as we have no children and don't haul much, except groceries.

22

23

25

26

27

NHTSA ID Number: 11565233 Incident Date January 3, 2024

Complaint Date January 12, 204

24 Consumer Location CALABASAS, CA Vehicle Identification Number 5FNRL6H78KB****

Summary of Complaint Trunk is not properly sealed resulting in water getting into the trunk and corroding the tailgate control unit, this issue has been reported online hundreds of times. A week after my trunk flooded during heavy rain my car warning lights for the brake system, lane keep assist and several others lit up and wont work, the lights turn on and off intermittently - again this issue is being reported online by multiple owners. This is a known issue Honda refuses to acknowledge or resolve.

2

NHTSA ID Number: 11565805 **Incident Date** January 12, 2024 Complaint Date January 16, 2024

Consumer Location MOUNT HOLLY, NC 3

Vehicle Identification Number 5FNRL6H79LB****

Summary of Complaint 4

There is a water leak in the factory seals of the rear tailgate which causes the Power Tailgate Control Module to fail. The tail gate can no longer be closed/latched and 5 requires replacement and sealing of the water leak.

6

7

8

10

11

12

NHTSA ID Number: 11566120 **Incident Date** January 10, 2024 Complaint Date January 17, 2024 Consumer Location OXFORD, PA

Vehicle Identification Number 5FNRL6H77KB****

9 **Summary of Complaint**

Power tailgate began to malfunction first by opening slowly or not opening at all. Once open, would not close automatically. Would require a lot of manual force. Then, a "Power Tailgate Problem" error began to show on the dashboard. We took it to our local mechanic within about a week's time. They found the following 9 electrical codes: Power Tailgate Control Unit Internal Error Power Tailgate Right Touch / Pinch Sensor Circuit Malfunction Power Tailgate Left Touch / Pinch Sensor Circuit Malfunction Tailgate Closer Unit Half Latch Switch Circuit Malfunction Power Tailgate Sensor Pulse "A" Circuit Malfunction Power Tailgate Sensor Pulse "B" Circuit Malfunction Power Tailgate Drive Motor Circuit Malfunction Left Power Sliding Door Touch / Pinch Sensor Signal Error Left Power Sliding Door Touch / Pinch Sensor Signal Error They then found that the water was on/in the Power Liftgate Control Unit stemming from a leak somewhere in the body, probably around the D pillar. The Power Liftgate Control Unit will be replaced. The local mechanic recommended contacting Honda or a body shop to find the location where the water is entering the car.

NYE, STIRLING, HALE, MILLER & SWEET

NHTSA ID Number: 11566344 **Incident Date** August 11, 2023 Complaint Date January 18, 2024 Consumer Location TAMPA, FL

Vehicle Identification Number 5FNRL6H73KB****

19 **Summary of Complaint**

Water leaked through the roof causing the tailgate motor to fail. There are separations 20 in the body seams above the tailgate. The vehicle has not been an accident.

21

25

26

27

28

18

NHTSA ID Number: 11566712 **Incident Date** December 1, 2023 22 Complaint Date January 20, 2024 Consumer Location HOUSTON, TX 23

Vehicle Identification Number 5FNRL6H76KB****

24 Summary of Complaint

A faulty body seam seal allowed rain to enter the body of the vehicle and infiltrate the power tailgate control module. On my vehicle, this produced the error message "Tailgate Problem". The tailgate would fail to open, open part way and then close, or attempt to open at random. There have been reports of tailgates opening while driving as a result of this problem. My dealer replaced the tailgate module and re-sealed the body seam where water was entering. This seam is where the top and side panels of the vehicle join near the driver's side tailgate hinge. This is a manufacturing defect in the body seam seal that is allowing this to happen. The problem has been extensively

operating the vehicle, creating a hazardous condition for occupants or for other motorists who might be affected by items falling out of the rear tailgate. INFORMATION REDACTED PURSUANT TO THE FREEDOM OF

INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

NHTSA ID Number: 11568068

Incident Date December 30, 2023

Complaint Date January 26, 2024 Consumer Location CASTLE HAYNE, NC 6

Vehicle Identification Number 5FNRL6H77JB****

7 Summary of Complaint

The power tailgate control module failed due to water leaking through holes in the seam. The power tailgate problem light came on when the issues began. I was unable to open the tailgate using the button by the driver's controls, the remote fob, or the exterior button on the tailgate. The only way to open the tailgate was the manual release on the interior tailgate. There was constant beeping while driving forward or in reverse. We removed the power tailgate control module, and there was obvious corrosion around the entire part. We applied seam sealer on the driver side roof rail and installed a new ptg control module. The new module began having similar issues approximately 2 weeks later. We removed it, and could see obvious corrosion beginning on one side of the ptg control module. We applied seam sealer above the rear tailgate window and attempted to clean the affected areas on the ptg control module in hopes that it will work again. The power function of the tailgate is not working, but the power tailgate problem light is not on and there is no beeping. I am now able to open the tailgate manually using the exterior button on the tailgate. Driver's control button, remote fob button, and button on the tailgate to close it do not work.

NHTSA ID Number: 11568060 **Incident Date** January 26, 2024 Complaint Date January 26, 2024

Consumer Location TÁUNTON, MA

Vehicle Identification Number 5FNRL6H7XJB****

Summary of Complaint

POWER LIFT GATE AND POWER SLIDING MINIVAN DOOR DO NOT WORK LEAK IN BODY CAUSED ELECTRICAL SHORT AND CORROSON OF LIFTGATE POWER CONTROL UNIT. BAD DESIGN SAFETY ISSUE. DANGER OF CHILD ENTRAPMENT. SHOULD BE RECALL AND HONDA SHOULD FIX

21

26

27

28

3

4

5

10

11

12

13

15

16

17

18

19

20

NHTSA ID Number: 11568287 22

Incident Date January 25, 2024 **Complaint Date** January 28, 2024 23

Consumer Location HÖT SPRINGS NATIONAL PARK, AR

Vehicle Identification Number 5FNRL6H73JB**** 24

Summary of Complaint 25

Power tailgate problem. Middle both passenger side door did not latch. Power tailgate cannot open automatically. It happened recently, and happened every year as far as I remember, when raining season, or winter time. It just happened few days ago. Passenger side door did not latch. I was driving with baby in car seat, on freeway, when door latch did not lock properly. My wife had this incident as well, and called Honda dealer, and they may or may not repaired the latch, and we rarely have this incident anymore after my wife called Honda dealer, cause she freaked out door was open

3

4

8

9

10

14

15

16

17

19

20

21

22

loosely while driving. But on left side, occasionally cannot open or closed, not as 1 extreme as before we complained to dealer.

NHTSA ID Number: 11568464

Incident Date January 26, 2024 **Complaint Date** January 29, 2024

Consumer Location KANNAPOLIS, NC Vehicle Identification Number 5FNRL6H71JB****

Summary of Complaint 5

2018 Honda Odyssey motorized tailgate has completely stopped working. Will not open. Numerous accounts say this is due to water getting into the rear tailgate control module and have had tremendous amount of rain this week. Have not had it looked at 6 by dealer yet but must be fixed. Warning message appeared twice on dash 10 minutes 7 before the failure.

NHTSA ID Number: 11568412 **Incident Date** January 3, 2024

Complaint Date January 29, 2024 Consumer Location JACKSON, SC

Vehicle Identification Number 5FNRL6H70JB****

Summary of Complaint 11

Dash displays error message "Power Tailgate Problem". Tailgate does not open AT ALL with either of the following methods- key fob, button on dash, or button on tailgate. It is stuck and poses a significant safety issue. What if we had a accident, all doors were stuck, and needed an exit out the back of the vehicle? The tailgate is totally inoperable and Honda needs to fix this issue as it is an extremely common issue and not very cheap to repair.

NHTSA ID Number: 11570351 **Incident Date** January 5, 2024 Complaint Date February 6, 2024

Consumer Location NEW PALTZ, NY Vehicle Identification Number 5FNRL6H78JB****

Summary of Complaint

A defective/leaking seal in the rear of the vehicle area caused water damage and corrosion on the tailgate control unit. As a result of the control unit failure the blinkers and lights stopped working while driving. In addition rear tailgate does not open. Dealer confirmed the issue, fixed the seal and replaced control unit. Research shows this is a recurring problem on this model vehicle.

NHTSA ID Number: 11571861 Complaint Date February 14, 2024

Incident Date February 12, 2024 Consumer Location VIRGINIA BEACH, VA 23

Vehicle Identification Number 5FNRL6H79JB****

24 Summary of Complaint

The rear lift gate is not opening. The lift gate motor and latch have been replaced. The lift gate module seems to have water/moisture after a rain storm causing the gate to not 25 open. Their is an error on the display saying there is a lift gate error and the car is 26 beeping while driving.

NHTSA ID Number: 11574361 27 **Incident Date** January 3, 2024 Complaint Date February 26, 2024 28

5

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

13

14

16

17

18

19

20

21

22

23

24

25

26

27

1

Consumer Location Unknown

Vehicle Identification Number 5FNRL6H71JB****

Summary of Complaint

Rear tail gate hatch Anytime it rains the hatch will open and faults out which ultimately causing it to not close or open tailgate fault shows up on the dash and does not function anymore do to water collecting in electrical module that controls hatch due to faulty design

- NHTSA ID Number: 11575085 **Incident Date** March 2, 2024
- Complaint Date March 2, 2024 6 Consumer Location Unknown
- Vehicle Identification Number 5FNRL6H71JB**** 7

Summary of Complaint Rear tail gate will not open even manually due to water getting inside of control module 8 due to faulty design which causes water to go into the module and fry it would open and

close randomly when it would rain now it has stopped working all together no indicator 9 on dash anymore I guess this last rain finished it off terrible design very disappointing with Honda this is a major issue that needs to be fixed 10

NHTSA ID Number: 11575401 11 **Incident Date** February 13, 2024 **Complaint Date** March 4, 2024 12 Consumer Location LOWGAP, NC

Vehicle Identification Number 5FNRL6H70KB****

Summary of Complaint

My Honda odyssey 2019 started with issues turning all bunch of light in the dash, the brake system light, the road departure mitigation system light, keyless remote not working properly had to press 2 times to turn on or off, battery will drain and not work properly. The keyless fob will not unlock the car, the back sliding doors would not open at all. My car left me 2 times and I had to call geico for road assistance. I took it to the closest dealer to get it checked they tought it was the battery so we had warranty on it and they replaced it. They tought the problem was fix but again all lights came back again. This happened 3 times in the nissan dealer. This past month and a half I have being dealing with my vehicle. So this weekend we decided to take it to the Honda dealer that's Ihr away from my home, with all the lights on again, scare that she would turn off on the highway. No turn light signals working, no hazard lights working either. Finally today I got an answer from the dealer they said that the cars tailgate left side factory seal, that's like a rubber its falling off little by little and it messed up the computer that's next to the back left panel of the driver side. They say that this is wear but I have heard of too many vehicles being damage on the same spot and it starts with the tailgate. They want to charge me \$673.89 to replace the tailgate control unit and that if that didn't first he madeless that the tail and the same spot and it starts with if that didn't fix the problem that I had to rewired the vehicle again and that was going to be be \$4790.78. I would love to see Honda to do a recall on this, this is something that has to do with factory issue, I don't think owners should pay for something wrong they are doing while building this mini vans. I have warranty on the vehicle and they are saying that would not cover the repair because its a water damage. This keeps happening to almost all the Honda mini vans. Pls do the search and you will see many people complaining about it. Thank you!

NHTSA ID Number: 11575964 Incident Date March 6, 2024 Complaint Date March 7, 2024

Consumer Location METUCHEN, NJ

Vehicle Identification Number 5FNRL6H75JB**** 28

1 Hello, my name is [XXX]. I have a 2018 Honda Odyssey that I bought brand new 6 years ago from Open Road Honda in Edison, New Jersey. We received a notification of 2 the tailgate malfunctioning out of the blue yesterday evening. It was raining the whole day yesterday. Upon checking the internet, we found this to be an issue faced by 3 multiple Honda Odyssey owners and a dedicated thread discussing this in the Honda Odyssey Forum. Link to it is here: [XXX] After doing a little bit more research, we 4 found a potential problem to be a malfunction due to water going into power tailgate module and this could be caused by some welding defects from Honda. We decided to 5 remove the fusebox cover in the back left of the car (driver side) and found that there was water inside. We have sent the car to our mechanic to resolve the issue. Please see 6 pictures and video attached for your review. This also has the VIN number for our car. But, since this seems to be a manufacturing defect and it is going to cost a lot to fix, we 7 would appreciate Honda taking action on this. We would like to take this to a dealership for issue resolution with Honda facilitating and paying for the repairs since it is a manufacturing defect. Please advise us on next steps. Thanks, [XXX] INFORMATION 8 REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

10

13

14

16

17

18

NHTSA ID Number: 11576494

11 **Incident Date** March 5, 2024 Complaint Date March 10, 2024

Consumer Location SENOIA, GA 12

Vehicle Identification Number 5FNRL6H77JB****

Summary of Complaint

There is an electrical drain causing the battery to drain to the point where it will not start. Alternator was replaced, then the issue persisted. Most recent problem include the power tailgate opening on its own. Rear power tailgate issue. The rear tailgate will attempt to open while driving, but the warning sound chimes and alerts to the problem. If the vehicle is left unlocked the tailgate will open itself. The power tailgate button in the driver seat does not work. The close button on the bottom of the door is illuminated (has power) but will not close the door. The soft rubber button above the license plate will engage the motor to lift the tailgate, but not to close it. Others have filed complaints about a water leak impacting the rear control board and causing it to fail. Leak may be from the fin on the roof or related to the cracking and rotting seal on the bottom of the rear windshield.

19

20

23

24

25

26

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

NHTSA ID Number: 11576998

Incident Date January 26, 2024 Complaint Date March 12, 2024 Consumer Location PORTLAND, OR 21

Vehicle Identification Number 5FNRL6H58JB****

22 Summary of Complaint

Our Tailgate is having an issue that triggered a safety issue with my wife driving on a highway then 3 lights popped up and car entered a limp mode, transmission issue, emissions issue, tailgate issue since then car is behaving normally but the tailgate latch is opening when we start the van and not working from fob (unlock) or exterior tailgate button. I have read other owners having an issue where the tailgate control module is getting submerged by water causing the unit to short and cause these issues. A car entering limp mode on the highway poses a threat to our family and others, I hope to see a solution in the near future.

NHTSA ID Number: 11577896 27 **Incident Date** March 8, 2024 Complaint Date March 17, 2024 28

4

5

6

7

8

Summary of Complaint

A water leak above the tailgate control module flooded it to the point that it operated erratically and would raise and lower the tailgate randomly or not work at all. I plan on replacing the module myself but will retain the old one. Anytime the entry or exit points on a vehicle open randomly cannot be a safe condition. The dealer charges \$130 for any inspection or diagnostic so no I am not paying them to tell me something is broken. The vehicle currently is showing a "Power Tailgate Problem" and a yellow box with "TAILGATE" in it on the dash display and is currently unresponsive to any input that would operate it: remote, tailgate buttons, and driver button. The power locking system is still operable. The Odyessy forums clearly describe multiple occurrences of this failure and the culprit is a water leak in rear window or rear section of roof trim strip on the drivers side. My module did have water in it when I opened the plastic case it is contained in. Cleaning and drying it restored operation for about 3 days. Thanks for your help!

9

10

12

13

14

NHTSA ID Number: 11578780

Incident Date March 1, 2024

Complaint Date March 21, 2024 11

Consumer Location GOODYEAR, AZ

Vehicle Identification Number 5FNRL6H53KB****

Summary of Complaint

Rear tailgate will occasionally pop open while driving for no reason. Often times when parked rear tailgate latch will not open it. Takes several attempts to get it open, sometimes have to open another door to get it to work.

15

16

17

18

19

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

NHTSA ID Number: 11578173 Incident Date March 2, 2024

Complaint Date March 18, 2024

Consumer Location GERMANTOWN, MD

Vehicle Identification Number 5FNRL6H78JB****

Summary of Complaint

After rain, the next day, I get error tailgate problem on my dashboard. I can no longer open it using my remote or from the front panel of my van. I saw many complaints of similar issue out there. This should have been a recall due to manufacture failure.

20

NHTSA ID Number: 11579605

Incident Date February 1, 2024 **Complaint Date** March 26, 2024 21

Consumer Location KINGSLEY, PA

Vehicle Identification Number 5FNRL6H84JB**** 22

Summary of Complaint 23

Right Power door will not open or close with buttons or key fob. Must open/close manually. The doors are too hard to open manually for smaller children and even some 24 adults making it a safety concern in case of emergency. This started intermittently a year ago and is now a constant. Tailgate has been opening and closing on its own, even when locked while parked as well as when the idle stop is activated while in drive. This is a concern that someone can get in the vehicle when unattended. It also shuts (and didn't stop) when someone was standing in the opening while removing something when it occurred. This started about a month ago. I was told to take it to a dealer and 26 pay them to diagnose it. The dealers have a wait list and it's also not in my budget. These are real concerns and I feel Honda isn't taking ownership of the dangers.

28

NHTSA ID Number: 11580032 1 Incident Date March 8, 2024

Complaint Date March 29, 2024

Consumer Location HANOVER, MD **Vehicle Identification Number** 5FNRL6H75JB****

Summary of Complaint

Power Tailgate is not functioning and the trunk opens on its own. Yes, available for 4 inspection. The trunk opening on its own puts the safety of everyone in the car at risk.

I had the same issue 9 months ago, the dealer charged me \$1200 to fix it. The dealer inspected it and stated it was due to a water leak that damaged the control module for the Power Tailgate. Nothing prior, a "Power Tailgate Problem" warning appeared on the dashboard, and the Power Tailgate stopped working.

7

9

6

NHTSA ID Number: 11581763

Incident Date April 8, 2024 Complaint Date April 8, 2024 8

Consumer Location TIFFIN, IA

Vehicle Identification Number 5FNRL6H78JB****

Summary of Complaint 10

Water getting into rear liftgate control module. Had to replace seal and module.

11

13

14

15

NHTSA ID Number: 11582273

Incident Date April 7, 2024 12

Complaint Date April 11, 2024

Consumer Location EAU CLAIRE, WI

Vehicle Identification Number 5FNRL6H76JB****

Summary of Complaint

Summary of Complaint

Water leaks into tailgate control module causing tailgate not to work. Replaced module, problem came back after 3 weeks. This is a common issue for the current generation Odyssey.

16 17

18

NHTSA ID Number: 11582291 Incident Date April 8, 2024 Complaint Date April 11, 2024

Consumer Location MINNEAPOLIS, MN

Vehicle Identification Number 5FNRL6H75JB****

19

20

21

24

25

26

28

It is available for inspection on request. Lost blindspot info, lost use of turn indicators, rear door hatch malfunction, several warnings flash up while driving. I was in a busy area and didn't have a way to signal my movements, screen flashing warnings was terrifying, the van felt like it might turn off at any moment. Before the most recent incident, we had brought the van to Honda dealer for repair, for similar issues that occured at start-up, they found water in the power control unit in rear left area of van

22 that caused corrosion and short-circuit. No body damage or alterations to vehicle. Replaced unit and after rainy weather problems recurred at start up and power down, 23

then while driving, they tested the battery and it was almost dead (the battery was only 1 month old) replaced battery. Problems recurred and water found again, significant leak suspected but not found yet as the service department won't evaluate the seals, and told us it's a body-shop task, summary: intermittent left-side passenger door and rear

hatch door malfunction, blind spot system warnings/loss, loss of turn indication, brake system warnings, other system warnings, difficulty starting the car and turning the car off, brand new battery drained while the car was parked and turned off. This manufacturing defect should be addressed by Honda, seals should not fail when exposed

to regular conditions. Water should not enter the vehicle and short out an important

component leading to several malfunctions that could cause loss of important systems

4

1

NHTSA ID Number: 11582804

and rear-door latch while driving.

Incident Date April 2, 2024 3 Complaint Date April 13, 2024

Consumer Location MINNEAPOLIS, MN

Vehicle Identification Number 5FNRL6H79JB****

Summary of Complaint 5

power tailgate control module fail due to water a leak in rear driver side area.

6

8

10

11

12

NHTSA ID Number: 11584161

Incident Date April 19, 2024 7 Complaint Date April 19, 2024

Consumer Location CARMI, IL

Vehicle Identification Number 5FNRL6H74JB****

9 **Summary of Complaint**

There is water leaking through the seams of my Van from where it wasn't welded and sealed properly, My tailgate opened on the highway today while I had my 7 kids in the vehicle while it was pouring down rain. I could not get my tailgate to stay closed and keep getting a power tailgate problem on my dashboard. My tailgate will no longer stay latched it automatically opens on its own and refuses to stay shut. I looked at the control module and it was completely soaked in water and can see the water leaking from the top of my vehicle in between the exterior frame and the interior frame. There are holes in the welding. They're quoting me almost \$1000 to fix the mistake they made while manufacturing the vehicle. I currently have a bungie chord keeping my tailgate shut but it continously beeps from where it's trying to open automatically. Definitely the scariest day of my life today. This needs to be dealt with ASAP. Today could have been much worse than it was. Honda needs to be held accountable before someone dies over this. There is no reason why my tailgate should have automatically opened on the highway doing 65mph with my 7 children in the car.

18

20

21

22

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

NHTSA ID Number: 11584215 **Incident Date** February 12, 2024 Complaint Date April 20, 2024 Consumer Location Unknown

Vehicle Identification Number 5FNRL6H71LB****

19 **Summary of Complaint**

Power tailgate module exposed to water due to manufacturer defect in sealing above module. causing various electrical systems to fail including safety features. I do have the damaged module. Tailgate opened and wouldn't close, when car in motion. Unable to use vehicle, the amount of electric items, due to fear brakes or transmission would fail while driving minivan full of young children Vehicle had warning light shortly after heavy rain. Was intermittent.

23

24

NHTSA ID Number: 11585688 **Incident Date** March 19, 2024

Complaint Date April 28, 2024

Consumer Location ABINGDON, MD 25

Vehicle Identification Number 5FNRL6H70KB****

26

Summary of Complaint The vehicle's tailgate stopped working and a series of distracting alerts repeatedly popped up on the instrument panel. Upon inspection, the liftgate control module had a significant amount of corrosion on the pins and on the circuit board itself, despite the

28

fix the problem because the connector pins are corroded and dirty.

12

13

16

17

18

19

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

1

NHTSA ID Number: 11587814

Incident Date March 29, 2024 Complaint Date May 9, 2024

4 | Consumer Location CÁRNEGIE, PA

Vehicle Identification Number 5FNRL6H75KB****

5 | Summary of Complaint

Water leaked into the back of my van through the plastic molding at the top of the lift gate. I was told the water ruined the control module. The part I was told would rrun \$850 to replace. I looked the control module online at a gunuine Honda parts catalogue & it's \$121. They tell me there is no guarantee that this will work. If it does not, then they recommend the replacement of the rear wiring harness which lists at the same Honda parts site to \$2,101.64 but this dealership wants to charge \$8,500 plus \$900 for

surrounding area seeming dry. Replacement of the control module did not completely

Honda parts site fo \$2,101.64 but this dealership wants to charge \$8,500 plus \$900 for new carpeting. Looking at the auto blogs, it seems that this is a recurring issue with the

9 | 2018-2019 Odysseys.

10 NHTSA ID Number: 11588416 Incident Date May 13, 2024

11 | Complaint Date May 13, 2024

Consumer Location FLÉMING ISLAND, FL

Vehicle Identification Number 5FNRL6H73KB****

|Summary of Complaint

What component or system failed or malfunctioned, and is it available for inspection upon request? the tailgate will not open. Yes, I can have it inspected. How was your safety or the safety of others put at risk? This limits the ability to use the tailgate. Has the problem been reproduced or confirmed by a dealer or independent service center? I have brought the car into the dealership to fix the tailgate. The motor was replaced and they stated they sealed the back to prevent water from getting in. It has since broken again and currently it will not open. Has the vehicle or component been inspected by the manufacturer, police, insurance representatives or others? The first time it broke the dealership inspected and fixed the problem. It is now broken again and I haven't brought it into the dealership yet. Were there any warning lamps, messages or other symptoms of the problem prior to the failure, and when did they first appear? I got a tailgate error multiple times, also the battery was draining really quickly - which I think was due to the trunk issue.

20 **NHTSA ID Number:** 11591001

Incident Date May 27, 2024 Complaint Date May 28, 2024

21 | Complaint Date May 28, 2024 | Consumer Location FORT MITCHELL, AL

22 | Vehicle Identification Number 5FNRL6H7XJB****

| Summary of Complaint

Power tailgate issue continues to happen. The module is somehow getting water damage and shorting out. This is the second time in a year that I have to replace the module. I can't even manually open my trunk without having to climb through the car and undo

the latch from the inside

25 **NHTSA ID Number:** 11592225

26 **Incident Date** May 28, 2024 **Complaint Date** June 3, 2024

27 | Consumer Location HAMPTON, VA

Vehicle Identification Number 5FNRL6H72JB****

28 | Summary of Complaint

7

9

10

11

12

13

14

16

17

18

19

20

21

22

23

24

25

28

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

NHTSA ID Number: 11593386 Incident Date April 12, 2024

Complaint Date June 10, 2024 Consumer Location BATON ROUGE, LA

Vehicle Identification Number 5FNRL6H74KB****

8 Vehicle Identification No Summary of Complaint

A water leak has ruined TWO power liftgate control modules. The water leak probably comes from the roof or driver rear window welds. I replaced one module two months ago and the new one has also malfunctioned due to water intrusion. This causes the liftgate to be stuck open or closed and could potentially open when driving!

NHTSA ID Number: 11593412 Incident Date March 3, 2024

Complaint Date June 10, 2024

| Consumer Location SEATTLE, WA | Vehicle Identification Number 5FNRL6H76KB****

Summary of Complaint

The issue I am experiencing is a power tailgate control module failure, specifically part# 74970-THR-A12. The part is located on the driver side rear, and the issue appears to be due to a water leak coming between body seams and slowly dripping down into the module. Over time the water damage seeps into the control module casing and causes corrosion on the circuit board. This, then, renders the power tailgate inoperable. In my case, it just suddenly stopped working. A couple weeks, while the tailgate still did not work, I did receive a message saying "tailgate open" while I was driving. But, that issue went away on its own, and the tailgate didn't appear to actually be open. It is unclear if this type of electrical failure could also cause a tailgate to open unexpectedly while driving. Looking up this issue online, it appears that many other Odyssey owners have experienced the exact same issue (water leak and corrosion on control module). This should be considered for a recall given that so many drivers have experienced the exact same issues under the exact same circumstances. It seems like the issue could be solved by simply determine where the leak is occurring from. While my Odyssey is still under an extended warranty, the dealer charges to perform a diagnostic do not make it worthwhile for me to have them determine if it is covered, and I will choose to replace the part on my own. Below I have attached 4 photos showing my specific circuit board with water damage, plus the area in which the control module sits in the car, where you can see rust due to water seepage. I also experienced rapid and sudden battery drain in the past, and others in the forums that experienced this tailgate issue have also noted that they believe it may be related. Even after I replace the part, I am afraid of the issue reoccurring and/or the water leaks creating additional electrical problems in the car.

26 NHTSA ID Number: 11593819 Incident Date June 10, 2024 Complaint Date June 12, 2024

Consumer Location VIRGINIA BEACH, VA

Vehicle Identification Number 5FNRL6H71JB****

13

14

15

16

17

18

19

20

21

22

23

Water intrusion is causing failure of my liftgate module. The maintenance shop has identified this as the issue. After doing some research, this appears to no be a one time 2 situation as i have read of several other owners experiencing the same issue. Lift gate is not opening and potential of liftgate opening uncommand due to module failure. 3

NHTSA ID Number: 11594385 4 **Incident Date** June 14, 2024 Complaint Date June 14, 2024 5

Consumer Location PALM SPRINGS, FL

Vehicle Identification Number 5FNRĹ6H77JB**** 6

Summary of Complaint

The Control Module for the Power Tailgate experienced total failure due to water 7 damage, documented by the servicing dealership (attached service invoice) and demonstrated by the attached photos. The point of water intrusion could not be determined definitively, but cracks in the bonding location between the roof, rear 8 driver's side exterior D-pillar panel, and tailgate surround are the likely culprit (photos attached). Failure of the Module resulted in an unusable tailgate, except for a single manual lever on the inside of the vehicle, accessible behind a piece of plastic. It also 10 resulted in a ceaseless, loud, constant beeping on both the inside and outside of the vehicle when traveling at over 1 mph. This vehicle has never experienced an accident. 11

NHTSA ID Number: 11597496 Incident Date June 22, 2024 Complaint Date June 28, 2024

Consumer Location LOXAHATCHEE, FL

Vehicle Identification Number 5FNRL6H71JB****

Summary of Complaint

During my recent recall repair by Ed Morse Honda in Riviera Beach, FL, I was advised that the rear tailgate sensor was reported as "wet". I do the maintenance myself, so I passed on a repair at that time by the dealer. Today, I researched what might have failed both online and with my Alldatadiy subscription, and accessed the part. Indeed, the Liftgate Control Module was molded and need of repair/ replace. However, I have grandchildren now, and during the removal - realized that in a water accident or other hazard where power is lost, there is NO WAY for rear passengers to exit the van by the rear tailgate. There is NO readily accessible latch or pull to open the tailgate from the inside, and NO key nor latch available from the outside for outside assistance. Additionally, if a child is in need of exiting the rear tailgate, there is NO child safety pull to allow them to exit. During my research on how to repair the vehicle, I saw that this is an ongoing issue for this model of Honda. I like my 2018 Honda Odyssey very much, it is my second Odyssey (the first was totaled in a T-bone accident, where both wife and daughter walked away), but I believe a recall is needed for the water issue affecting the Tailgate Control Board for the short term, and safety mechanisms added for the long term. Note: I have images, but the web site is NOT allowing uploads of any .jpg nor .pdf's at this time.

24 NHTSA ID Number: 11603270 Incident Date July 18, 2024 Complaint Date July 18, 2024 25

Consumer Location WARNER ROBINS, GA

Vehicle Identification Number 5FNRL6H79KB**** 26

Summary of Complaint

The power tailgate would open, then after opening, the tailgate may slowly sag down. 27 Then it automatically closes within seconds. When going down to close, it beeps loudly. 28

NHTSA ID Number: 11604132 1

Incident Date July 18, 2024 Complaint Date July 23, 2024

2 Consumer Location FREEPORT, FL

Vehicle Identification Number 5FNRL6H7XJB****

Summary of Complaint

3

12

13

14

15

16

17

18

19

20

21

25

26

27

28

Vehicle stalls when pulling out into traffic! Terrifying with my 6 kids and I'm 4 immediately getting rid of this vehicle. Tried to have the fuel pump (current recall) replaced but Honda dealership has the vehicle for 6 DAYS! and still didn't have the part 5

in. Upon dropping the vehicle off the tailgate lift would not work properly. This van is

a load of garbage since they started using so many modules to control it! Extremely disappointed in Honda. They know all of these faulty parts and don't care enough to fix 6 them for the safety of the consumer. Absolutely horrifying the direction of the 7 automobile industry

8 NHTSA ID Number: 11604172

Incident Date July 23, 2024 9

Complaint Date July 23, 2024 Consumer Location JONESBORO, GA 10

Vehicle Identification Number 5FNRL6H78JB****

Summary of Complaint 11

Tailgate malfunction due to water seeping through tailgate resulting in tailgate module to stop working.

NHTSA ID Number: 11606778 **Incident Date** July 29, 2024

Complaint Date August 6, 2024

Consumer Location AUTRYVILLE, NC

Vehicle Identification Number 5FNRL6H72JB****

Summary of Complaint

Initial issue was that the power tailgate would not open at all. Took the vehicle to the dealership where they replaced the latch and the control unit that was completely fried. When I asked what could cause that, they said they didn't know. I already suspected water. Two days after picking the vehicle up from the dealership, the tailgate is now constantly opening and closing on its own. The only way to stop it is to turn off the vehicle and lock it. I searched online and found multiple posts from people with the exact same problem and almost all of them say it was water getting into the control unit. This poses an obvious safety concern since it could close on one of my kids. They would not be strong enough to stop it. I have reported the issue to Honda HQ and have recommended that the other people with the issue do the same.

NHTSA ID Number: 11608292

Incident Date August 12, 2024 22

Complaint Date August 13, 2024 Consumer Location ONTARIO, CA

23 Vehicle Identification Number 5FNRL6H9XJB****

24 Summary of Complaint

the right sliding door has had intermittent malfunction for years, often, the door will not work with an automatic function and must be pulled open or closed manually which is nearly impossible to accomplish. most often the right sliding door malfunction notification appears when driving at highway speeds which is extremely unsafe. this has been inspected by the dealership and no fix or resolution was provided, recently, all of the ADAS systems are intermittently malfunctioning, they work about 1 out of every 5 times the vehicle turns on LKAS, Auto Braking, Adaptive Cruise Control, are all affected, within the last week the internal camera system has been failing, audio stops

2

3

4

7

9

10

11

12

13

14

15

16

17

18

19

20

24

28

working, and most importantly the rear hatch has been closing on its own while i am standing underneath it loading the trunk. this is also very unsafe, it atleast beeps to warn that it is closing but i sometimes barely have time to get out of the way. yesterday while driving in the highway, two warnings appeared simultaneously for "transmission system problem" and "blind spot notification system error". the vehicle started again without the transmission system or blind spot error but i am very concerned about the degrading electrical system issues that i have been experiencing with this family oriented vehicle model.

5 **NHTSA ID Number:** 11608694

6 | Incident Date June 15, 2024

Complaint Date August 15, 2024

| Consumer Location HOUSTON, TX | Vehicle Identification Number 5FNRL6H74KB****

8 | Summary of Complaint

It is very common problem with 2018-2023 honda odyssey. Water leaks inside from the seam crack under roof drip trim. This water is dripping right on the tailgate control electronic module. And module is short circuit and dead. Now tailgate is either stays locked or stays open all the time as the latch is not operating at all. This is safety issue as if tail gate is not latched properly it can be open while driving on the road. Also with water leaking inside in trunk area it's a issue with growing mold under the carpet. It shows error message on instrument panel about trouble with tailgate system.

NHTSA ID Number: 11610125 Incident Date August 22, 2024

Complaint Date August 22, 2024 Consumer Location WELLESLEY, MA

Vehicle Identification Number 5FNRL6H93LB****

Summary of Complaint

This model has had a recall of the wire being to short and having faulty connections. I have replaced the wires module now 5 times. The last time it got replaced after a couple of months the screen on the car has gone blank and now they tell me the whole computer needs to be replaced. No LCD and no backup screen. This is absolutely ridiculous. Anything that can be done this car seems to be a electrical disaster.

NHTSA ID Number: 11610612 Incident Date August 24, 2024 Complaint Date August 24, 2024

Consumer Location POWELL, OH
Vehicle Identification Number 5FNRL6H7XJB****

21 | Summary of Complaint

My trunk was working anymore. I could not even open it manually. I had a shop that only works on Acura's and Honda's look at it. The control module for the trunk was wet and fried. I dont understand why it was wet in the first place since it was in seal box. This should be a recall on it. Please see attach pictures. I paid \$669 to have them

replaced it.

NHTSA ID Number: 11610805

25 **Incident Date** August 12, 2024 **Complaint Date** August 26, 2024

26 Consumer Location IVANHOE, NC

Vehicle Identification Number 5FNRL6H78JB****

27 | Summary of Complaint

There is a water leak in the body of the van (where the top and side are welded together). The water has caused damage to the electrical panel that controls the back door/liftgate.

The water damage is also shorting out and causing electrical damage and the battery to die very often. I have noticed many complaints about this. I believe this should be a recall because it is a flaw in the making of the vehicle and nothing I could have done to prevent it.

NHTSA ID Number: 11616232

4 | Incident Date July 27, 2024

Complaint Date September 24, 2024

5 | Consumer Location RICHMOND HILL, NY

Vehicle Identification Number 5FNRL6H77JB****

6 | Summary of Complaint

The tailgate malfunctions and the car does not register the tailgate as closed even if it is closed. The power tailgate ceases to be operational and the locks do not work. The cause is a defect in a seam which allows rain water to reach the control unit for the tailgate.

This was confirmed after an inspection at an official Honda dealer. This is a safety issue because it renders the car inoperable. The "tailgate open" warning signs and sounds flash. There is currently a Honda "Engineering Request for Investigation" released. It

can be accessed at the following link: [XXX] INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C.

552(B)(6)

3

11 **NHTSA ID Number:** 11616819

12 **Incident Date** September 26, 2024 **Complaint Date** September 27, 2024

Consumer Location ALLENTOWN, PA

Vehicle Identification Number 5FNRL6H74JB****

Summary of Complaint

What component or system failed or malfunctioned, and is it available for inspection upon request? TAILGATE STOPPED OPENING AND THEN OPENED UNEXPECTANTLY; VEHICLE IS AVAILABLE FOR INSPECTION How was your safety or the safety of others put at risk? TAILGATE OPENED WHILE DRIVING Has the problem been reproduced or confirmed by a dealer or independent service center? NO Has the vehicle or component been inspected by the manufacturer, police, insurance representatives or others? NO Were there any warning lamps, messages or other symptoms of the problem prior to the failure, and when did they first appear? WARNING ALERT THAT TAILGATE HAD FAILED AND WARNING WENT AWAY APPROXIMATELY 12 HOURS BOFORE TAILGATE UNEXPECTANTLY OPENED.

20

13

14

15

16

17

18

19

NHTSA ID Number: 11619349

21 | Incident Date June 1, 2024

Complaint Date October 11, 2024 Consumer Location OLNEY, MD

22 | Consumer Location OLNEY, MD | Vehicle Identification Number 5FNRL6H70JB****

23 | Summary of Complaint

Rear tailgate is inoperable because of water damage. The rear driver side seatbelt is wet, the floor of the trunk is wet, the water damaged the control module for the rear tailgate, it does not open.

25

26

NHTSA ID Number: 11619636

Incident Date December 1, 2022 Complaint Date October 14, 2024

27 Consumer Location TALLAHASSEE, FL

Vehicle Identification Number 5FNRL6H78JB****

28 | Summary of Complaint

This Honda Odyssey 2018 model has leak water on rear corner. You have to find out

where is leaking and fix it, if you don't fix water leak after you install new control unit it will happen again. To find out where is leaking is a major problem. Honda DO NOT

4

6

7

8

9

recall on it

1

2

Incident Date October 10, 2024 Complaint Date October 16, 2024

Consumer Location SARASOTA, FL 5

Vehicle Identification Number 5FNRL6H74JB****

Summary of Complaint

After weathering hurricane Milton, the rear liftgate on my 2018 Honda Odyssey will not open. No apparent damage was done to the vehicle, however after starting the van, the dash stated there is a power liftgate issue. This warning was not present before. After doing some research the issue appears to be the tailgate control module, as many other people have found this to be the case. Some people have said to open the tailgate from the inside using the manual latch. However, in my case after attempting to do so, the door remains stuck. A lot of people have pointed to water intrusion as the reason for a faulty Tailgate Control Module. If I am able to open the liftgate manually I intend to replace the faulty module.

11

10

12

13

14

15

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

16 17

18

19

20

21

22

23

24

25

26

27

28

NHTSA ID Number: 11620750 **Incident Date** September 23, 2023 Complaint Date October 19, 2024

Consumer Location NORTH FORT MYERS, FL

Vehicle Identification Number 5FNRL6H78KB****

Summary of Complaint The Tailgate Control Module failed on three different occasion on my 2019 Honda Odyssey mini van causing the tailgate to fail to be opened by fob or manually. This was caused by water leaking through the roof rail where there was a failure by the manufacturer to properly seal the area between the roof and body. I have two of the failed TCMs in my possession. On 2 different occasions the tailgate flew opened as I was driving at approximately 55 mph.At that time the tailgate could not be closed entirely and caused my battery to run down entirely. The problem has been confirmed by the local Honda dealership and another independent service center. A warning and beeping noice came on as the first sign of the problem. I have photos of the crack and what was done to try to remediate the problem. This problem has been recognized and occurred to many other owners of 2018 - present day Honda Odyssey mini vans.

NHTSA ID Number: 11623820 **Incident Date** November 1, 2024

Complaint Date November 6, 2024 **Consumer Location** Unknown

Vehicle Identification Number 5FNRL6H71KB****

Summary of Complaint

The power lift gate would not open with the button on the dash, the button on the door, or the button on the key fob. The only way I could open it was to crawl in the back of the van, remove the access panel for the lock mechanism, and use the lever to unlock the door. Upon troubleshooting the problem, it was determined that the power lift gate control module needed to be replaced. That fixed the issue, however Upon inspection on the old module, which is located inside the vehicle, behind the driver rear quarter interior panel, there was obvious signs the failure was due to severe water damage intrusion into the module.

NHTSA ID Number: 11627867 1 **Incident Date** November 27, 2024

Complaint Date November 28, 2024

Consumer Location KAILUA KONA, HI

Vehicle Identification Number 5FNRL6H76KB**** 3

Summary of Complaint

- Driver side rear frame next to tailgate has some holes at the welding site that allowed 4 water to get in between the frame and the interior of the car and have fried the power
- tailgate module. I have had to purchase a new power tailgate module due to this 5
- NHTSA ID Number: 11629098 6
- **Incident Date** December 4, 2024 Complaint Date December 5, 2024 7

Consumer Location WETUMPKA, AL

Vehicle Identification Number 5FNRL6H7XJB****

Summary of Complaint

- I just had several recalls completed on my van. The issue that they couldn't fix (which I have seen on so many message boards) my car stalls when starting from a stop. If I'm at a stop sign and press the gas nothing happens for 2-3 seconds and then it will catch 10 and take off throwing everything in the car and the people forward. It is terrifying! I've had it happen with cars approaching and just been a sitting duck, thank the Lord it engaged in time. This seems to be a very prevalent issue and I don't understand why a recall hasn't been done before someone dies. My trunk also doesn't work automatically 11 12 anymore and they said I had a leak that would be \$300 to diagnose and \$500 to fix. I know ther are lawsuits for both of these issues. Recalls need to be issued. 13
 - NHTSA ID Number: 11629862 **Incident Date** December 5, 2024 Complaint Date December 10, 2024 Consumer Location WATCHUNG, NJ

Vehicle Identification Number 5FNRL6H72JB****

Summary of Complaint

My power tailgate stopped working after heavy rain. Based on online research this is a known issue due to faulty roof sealing and water infiltration, leading to tailgate module corrosion. The issue was confirmed by dealership diagnostics. They confirmed module corrosion and water infiltration. Offering replacement and resealing at \$1069. https://www.carscoops.com/2024/11/honda-being-sued-because-some-odysseys-mayhave-a-leaky-tailgate-than-can-open-at-anytime/

20

2

8

14

15

16

17

18

19

- **NHTSA ID Number:** 11630901 21 **Incident Date** December 15, 2024
- Complaint Date December 16, 2024 22

Consumer Location PORTAGE, MI Vehicle Identification Number 5FNRL6H74JB**** 23

Summary of Complaint

- 24 My 2018 Honda odyssey EX-L had a power tailgate failure. It looks like the controls module has experienced water damage from a water leak. An independent service center
- has confirmed the issue. There was no warning before it happened and it is a safety issue as my tail gate cannot Be securely closed. This water leak looks to be manufacturer 26 error.
- **NHTSA ID Number:** 11632574 27 **Incident Date** December 21, 2024
- Consumer Location GARDEN CITY, NY 28

Vehicle Identification Number 5FNRL6H7XJB**** **Summary of Complaint**

Our 2018 Honda Odyssey minivan had water leaks intruding and collecting into the power tailgate control module on the driver-side rear compartment causing the tailgate

to become nonfunctional and not lock properly or open/close appropriately leading to a major safety issue where the tailgate may open or even not close during movement of the vehicle leading to significant risk to passengers with respect to accident or bodily

injury. This power tailgate issue appears to be caused by defective rear body seam seals from the manufacturer that allows water to leak into the rear driver's side panels and intrude into the module leading to damage and destruction of the module circuit board.

I have needed to purchase a replacement for the module (~\$200) and I have provided photos to show the water damage

7

11

12

13

14

15

18

20

1

3

4

5

6

NHTSA ID Number: 11632574

Incident Date December 21, 2024 **Complaint Date** December 27, 2024 8

Consumer Location GARDEN CITY, NY 9

Vehicle Identification Number 5FNRL6H7XJB****

Summary of Complaint 10

Our 2018 Honda Odyssey minivan had water leaks intruding and collecting into the power tailgate control module on the driver-side rear compartment causing the tailgate to become nonfunctional and not lock properly or open/close appropriately leading to a major safety issue where the tailgate may open or even not close during movement of the vehicle leading to significant risk to passengers with respect to accident or bodily injury. This power tailgate issue appears to be caused by defective rear body seam seals from the manufacturer that allows water to leak into the rear driver's side panels and intrude into the module leading to damage and destruction of the module circuit board. I have needed to purchase a replacement for the module (~\$200) and I have provided photos to show the water damage.

16 17

NHTSA ID Number: 11633116 **Incident Date** December 29, 2024 Complaint Date December 30, 2024 Consumer Location COMMACK, NY

Vehicle Identification Number 5FNRL6H78KB****

19 Summary of Complaint

Leak in roof rail seam causes interior water leak and fried liftgate opener. Known issue manufacturer is not willing to address. Recent class action: [XXX] INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5

U.S.C. 552(B)(6) 21

NHTSA ID Number: 11633401 22 Incident Date December 23, 2024 Complaint Date December 31, 2024 23 Consumer Location SNELLVILLE, GA

Vehicle Identification Number 5FNRL6H72JB**** 24

Summary of Complaint 25

The rear failgate stopped working. Upon investigation, there is structural issue with the body. There are holes near rear tailgate which allows to water to pass through. The water has damaged the rear tailgate motor and now the door is inoperable. This has been a common issue with Odyssey minivans 2018 and newer model. We have contacted honda regarding the issue and they refuse to accept any liability regarding the body defects.

28

5

6

7

8

NHTSA ID Number: 11634642

Incident Date July 1, 2023 2

Complaint Date January 7, 2025 Consumer Location BATON ROUGE, LA

Vehicle Identification Number 5FNRL6H74KB****

Summary of Complaint 4

The latch system on the back hatch has a defect that allows water intrusion which shorts out the electrical board, and renders it unusable. It has randomly opened while driving Now, the hatch will not manually open even when you take off the handle from the inside. It is a safety issue, and while searching for answers, you can see that this is a universal issue. The Honda dealership confirmed that this is an issue, and the fix is well over \$1,000. There were no warnings about this, even when it randomly opened on its own and wouldn't shut. This has been an ongoing issue since we purchased the vehicle in 2023. It is available for inspection.

9

10

12

13

Complaint Date January 10, 2025

11

Consumer Location SAN JOSE, CA

NHTSA ID Number: 11635334 Incident Date December 28, 2024

Vehicle Identification Number 5FNRL6H78MB**** Summary of Complaint

On 28-Dec-2024 I noticed the power tailgate stopped working on my 2021 Honda Odyssey. I tried to press the power tailgate button on the key fob, the button on the driver's side control panel, and the button on the tailgate itself, but none of them works. I did some research online and found out it's a common problem in 2018 to 2021 models and the cause was the failed Power Tailgate Control Unit due to water leakage through the cracks on the vehicle body. I opened mine and found there was water in the control unit box which might have caused short on the circuit board. I bought a new control unit a week later and it fixed the issue.

NYE, STIRLING, HALE, MILLER & SWEET 33 WEST MISSION STREET, SUITE 20 15 16 17 18

19

21

22

23

24

25

26

NHTSA ID Number: 11635802 **Incident Date** December 29, 2024 Complaint Date January 14, 2025

Consumer Location WEST POINT, NY

Vehicle Identification Number 5FNRL6H73JB****

Summary of Complaint 20

The seam seals on the rear driver's quarter panel of the vehicle are faulty and allowed water to flow into the cabin of the vehicle. The resulting damage was loss of function to the rear power lift gate, front seats, remote start and other key fob functions, as well as a dead battery(assumedly due to arcing on wet circuitry). The damage rendered the lift gate inoperable as I it initially closed but came open during operation. We continued to receive a power lift gae problem on the "Heads Up Display" but the power gate would not open or close, electrically or manually. After a few days the gate opened but would not close, rendering the vehicle unsafe to operate. Furthermore, the battery was dead and would not start. Had this incicdent not occurred in our driveway we could have been susceptible to being stranded in sub-freezing

temperatures with kids. The vehicle was taken to a dealer and they confirmed a roof leak was a cause of the water incursion. The power lift gate module and floor harness were damaged causing failures to lift gate operation and other electronics. It will cost \$7000 to have it repaired at the local Honda dealer. Pending completion of repairs and paperwork for submission.

Incident Date January 18, 2025 Complaint Date January 18, 2025

Consumer Location HÓSCHTON, GA

Vehicle Identification Number 5FNRL6H70KB**** 3

Summary of Complaint

Water intrusion near rear tailgate control box. The circuit board was ruined by water 4 and the automatic tailgate was at first malfunctioning and then would not function at

all. The circuit board had to be replaced. 5

NHTSA ID Number: 11639122 6

Incident Date January 3, 2025 Complaint Date January 28, 2025

Consumer Location WEST CHESTER, OH

Vehicle Identification Number 5FNRL6H77JB****

Summary of Complaint

- The Tailgate Control Module (TCM) was infiltrated with water due to a crack in the 9 seam on the rear driver side panel. This caused the tailgate to be unusable and no longer latch as a result of no power to the tailgate latch. The TCM (Part #: 74970-
- 10 THR-A12) had to be replaced as well as all seams needed to be sealed.

11

13

14

7

8

2

NHTSA ID Number: 11639382

Incident Date January 9, 2025 Complaint Date January 29, 2025 12

Consumer Location BÉLLÉVILLE, NJ

Vehicle Identification Number 5FNRL6H77JB****

My 2018 Honda Odyssey experienced a heavy snowfall in January 2025. The control panel displayed an alarm, Power Tailgate Problem, and the trunk door could not be opened. I asked a professional who pointed out that it is usually due to water intrusion into the control unit located on the rear driver's side body panel, which causes the tailgate to fail to open, close normally, or even open accidentally. They believe that this is a manufacturing defect caused by the manufacturer and there is a safety hazard.

16 17

18

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 20

NHTSA ID Number: 11640810

Incident Date December 3, 2024 Complaint Date February 5, 2025

Consumer Location CHAMPAIGN, IL 19

Vehicle Identification Number 5FNRL6H70JB****

Summary of Complaint 20

Leakage through the top driver's side pinch weld near the rear of the vehicle has

21 allowed water to infiltrate the power tailgate control module and render it sporadically operable. This has affected the vehicle main computer, causing unreliable operation of

powered vehicle exit doors. 22

NHTSA ID Number: 11641592 23

Incident Date February 7, 2025 24

Complaint Date February 9, 2025 **Consumer Location HOUSTON, TX**

Vehicle Identification Number 5FNRL6H77KB**** 25

Summary of Complaint

I have had the trunk struts and power module replaced twice due to water leaks into 26 the compute module of my trunk. It has cost me headaches and thousand of dollars to

have it fixed. This issue should be recalled to fix and for a reseal of the trunk. My dash 27 has a power lift gate error show up and will not open anymore. Also it will not stay

open as well and slowly just close itself. 28

Santa Barbara, California 93101

Consumer Location CONROE, TX Vehicle Identification Number 5FNRL6H78KB****

Summary of Complaint

1

2

3

4

5

6

7

8

9

10

11

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

The power tail gate stopped working on 1/28/2025. After diagnosis the power tail gate and it's controls on passenger side rear control panel it is observed that there is water on the controls module. Part 74970-THR-A12Control Module for tailgate has been taken out and found that the water coming though it's sockets. The \$200 new control module will temporarily fix the issue but the defective rear body seam seals made of polyurethane that allow water to leak into the rear driver's side panels can cause the following issues. The tailgate opens and closes at random, The tailgate stays open or fails to close, Tailgate short circuits and causes a fire, Water leaks cause mold and rusting. I request Honda to take responsibility of the issue and fix the problem making sure it meet the safety standards.

NHTSA ID Number: 11643461 Incident Date February 14, 2025 Complaint Date February 18, 2025 Consumer Location OPELIKA, AL

Vehicle Identification Number 5FNRL6H7XLB****

12 | Summary of Complaint

I have had 3 Power Tailgate modules fail due to water leaks in the rear panel or window of the vehicle. I have had 2 leaks repaired and two modules replaced within a 6 month period (June '24 and December '24). 6 weeks later (Feb 14, 2024) have had the 3 module fail due to water intrusion following a heavy rain.

- 137. Consumers have not just complained to NHTSA, as the internet is replete with other complaints from consumers, many of which detail their interactions with Defendants' authorized dealerships, and as such, Defendants have actual knowledge of these consumer complaints too.
- 138. On September 2, 2021, a user posted to an Odyssey owner's forum where they recounted their experience with a malfunctioning tailgate on their Class Vehicle. In addition to numerous posters indicating that the root cause was water intrusion, many posters stated they brought their Class Vehicle to Honda dealerships for diagnosis (e.g. on October 11, 2011: "Having the same issue and dealer replaced the control unit couple of times under warranty couple of months back. Now dealer is giving up saying water leak coming from some where and asking to take it to body shop. Anyone know where is the exact leak for this issue? Looks like it more a design flaw and safety issue.").

⁸ https://www.odyclub.com/threads/2018-ex-l-nav-res-power-tailgate-problem-error.365335/ (last visited February 28, 2025).

139. On February 4, 2022, a user posted to an Odyssey owner's forum where they recounted their experience with the malfunctioning tailgate on their Class Vehicle which was opening on its own. The user relays that they had been to the Honda dealership twice regarding the issue. Numerous users posted that the root cause was likely water intrusion into the tailgate control module, and a number of posters indicated that they had the same issue and reported it to Honda's corporate customer service as well as Honda's dealerships.

- 140. Despite Honda's knowledge of the Sealant Defect, one owner of a Class Vehicle was quoted over \$8,000 for the necessary repairs in January of 2024 by an authorized Honda dealership.¹⁰ Other posts indicate similar quotes from authorized Honda dealerships.¹¹
- 141. Reddit users have recounted similar issues and likewise notified Honda's authorized dealerships regarding the issues. One poster had the issue occur and took the vehicle back to the Honda dealership, which "discovered that the roofline seam above the lift rear window in front of the liftgate was leaking." Other posters in the same thread also reported similar experiences with the Sealant Defect at Honda's authorized dealerships. Additional Reddit posts were made regarding the Sealant Defect that similarly state the issue was diagnosed by Honda's authorized dealerships. Another

https://www.reddit.com/r/HondaOdyssey/comments/19eeatk/water_leakerratic_electrical_issues/ (last visited February 28, 2025).

https://www.reddit.com/r/AskMechanics/comments/1c6euqy/honda_odyssey_2018_rear_tailgate_control_unit/ (last visited February 28, 2025);

https://www.reddit.com/r/HondaOdyssey/comments/1bcy08w/2020_power_tailgate_failure/

⁹ https://www.odyclub.com/threads/power-tailgate-issue-2018-exl-safety-concern.367379/ (last visited February 28, 2025).

¹⁰ https://www.odyclub.com/threads/over-8000-repair-bill-2018-honda-ex-l-for-power-tailgate-failure-and-other-issues-do-not-buy-a-2018-odyssey-i-now-hate-honda-for-life.376178/ (last visited February 28, 2025).

¹¹ <u>https://www.odyclub.com/threads/2018-power-tailgate-failure-dead-battery-from-body-leak.371746/page-2</u> (last visited February 28, 2025).

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

thread from three years ago states that the Honda dealership diagnosed the Sealant Defect as a "manufacturer issue" that the owner had to bring their Class Vehicle in for on two separate occasions. 14

CLASS ACTION ALLEGATIONS

142. Plaintiffs bring this action on behalf of themselves, and on behalf of the following nationwide class pursuant to Fed. R. Civ. P. 23(a), 23(b)(2), and/or 23(b)(3). Specifically, the nationwide class consists of the following:

Nationwide Class:

All persons or entities in the United States who are current or former owners and/or lessees of a Class Vehicle (the "Nationwide Class").

143. In the alternative to the Nationwide Class, and pursuant to Fed. R. Civ. P. 23(c)(5), Plaintiffs seek to represent the following state classes:

California Class:

All persons or entities who are: (1) current or former owners and/or lessees of a Class Vehicle; and (2) reside in California or purchased a Class Vehicle for primarily personal, family or household purposes, as defined by California Civil Code § 1791(a), in California.

Florida Class:

All persons or entities in Florida who are current or former owners and/or lessees of a Class Vehicle (the "Florida Class").

Maryland Class:

All persons or entities in Maryland who are current or former owners and/or lessees of a Class Vehicle (the "Maryland Class").

New Jersey Class:

All persons or entities in New Jersey who are current or former owners and/or lessees of a Class Vehicle (the "New Jersey Class").

(last visited February 28, 2025);

https://www.reddit.com/r/HondaOdyssey/comments/1bqxofu/water_intrusionagain/ (last visited February 28, 2025).

¹⁴ https://www.reddit.com/r/HondaOdyssey/comments/s90vqr/power_tailgate_issue/ (last visited February 28, 2025).

2

3

4

5

6

7

8

9

10

11

18

19

20

21

22

23

24

25

26

27

28

Washington Class:

All persons or entities in Washington who are current or former owners and/or lessees of a Class Vehicle (the "Washington Class").

- 144. Excluded from the Classes are Defendants, their affiliates, employees, officers and directors, persons or entities that purchased the Class Vehicles for resale, and the Judge(s) assigned to this case. Plaintiffs reserve the right to modify, change or expand the Class definitions.
- 145. Numerosity: Upon information and belief, the Classes are so numerous that joinder of all members is impracticable. While the exact number and identities of individual members of the Classes are unknown at this time, such information being in the sole possession of Honda and obtainable by Plaintiffs only through the discovery process, Plaintiffs believe that tens of thousands of Class Vehicles have been sold and leased in Florida and New Jersey, Washington, and hundreds of thousands nationwide.
- 146. Existence and Predominance of Common Questions of Fact and Law: Common questions of law and fact exist as to all members of the Classes. These questions predominate over the questions affecting individual Class members. These common legal and factual questions include, but are not limited to:
 - a. whether the Class Vehicles suffer from the Sealant Defect;
 - b. whether the defective sealant is common to all of the Class Vehicles;
 - c. whether the Sealant Defect causes tailgate control modules in the Class Vehicles to fail:
 - d. whether Defendants had a duty to disclose the Sealant Defect;
 - e. whether Defendants knowingly failed to disclose the existence and cause of the Sealant Defect in Class Vehicles;
 - f. whether Defendants' conduct violates the California Consumers Legal Remedies Act:

33 WEST MISSION STREET, SUITE 201 Santa Barbara, California 9310

NYE, STIRLING, HALE, MILLER & SWEET

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

- g. whether Defendants' conduct violates the California Unfair Competition Law;
- h. whether Defendants' conduct violates the Florida Deceptive and Unfair Trade Practices Act;
- i. whether Defendants' conduct violates the Maryland Consumer Protection Act;
- j. whether Defendants' conduct violates the New Jersey Consumer Fraud Act;
- k. whether Defendants' conduct violates the Washington Consumer Protection Act;
- whether Defendants' conduct violates the Song-Beverly Consumer Warranty Act for Breach of Implied Warranty;
- m. whether, as a result of Defendants' omissions and/or misrepresentations of material facts related to the Sealant Defect, Plaintiffs and members of the Class have suffered ascertainable loss of monies and/or property and/or value;
- n. whether, as a result of Defendants' omissions and/or misrepresentations of
 material facts related to the Sealant Defect, Plaintiffs and members of the
 Class have suffered an increased cost of maintenance related to the Class
 Vehicles; and
- o. whether Plaintiffs and Class members are entitled to monetary damages and/or other remedies and, if so, the nature of any such relief.
- 147. <u>Typicality</u>: Plaintiffs' claims are typical of the claims of the Classes since Plaintiffs purchased a Class Vehicle with the Sealant Defect, as did each member of the Class. Furthermore, Plaintiffs and all members of the Classes sustained monetary and economic injuries including, but not limited to, ascertainable loss arising out of Honda's wrongful conduct. Plaintiffs are advancing the same claims and legal theories on behalf of themselves and all absent Class members.

10

11 12

13

SANTA BARBARA, CALIFORNIA 93101 14

15

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 201

16 17

18

19

20 21

22

23 24

25

26

27

28

Adequacy: Plaintiffs are adequate representatives because their interests do not conflict with the interests of the Classes that they seek to represent, they have retained counsel competent and highly experienced in complex class action litigation, and they intend to prosecute this action vigorously. The interests of the Classes will be fairly and adequately protected by Plaintiffs and their counsel.

149. <u>Superiority</u>: A class action is superior to all other available means of fair and efficient adjudication of the claims of Plaintiffs and members of the Classes. The injury suffered by each individual Class member is relatively small in comparison to the burden and expense of individual prosecution of the complex and extensive litigation necessitated by Honda's conduct. It would be virtually impossible for members of the Classes to individually and effectively redress the wrongs done to them. Even if the members of the Classes could afford such individual litigation, the court system could not. Individualized litigation presents a potential for inconsistent or contradictory judgments. Individualized litigation also increases the delay and expense to all parties, and to the court system, presented by the complex legal and factual issues of the case. By contrast, the class action device presents far fewer management difficulties, and provides the benefits of single adjudication, economy of scale, and comprehensive supervision by a single court. Upon information and belief, members of the Classes can be readily identified and notified based on, inter alia, Honda's vehicle identification numbers (VINs), warranty claims, registration records, and the database of complaints.

150. Injunctive Relief: Pursuant to Fed. R. Civ. P. 23(b)(2), Honda has acted or refused to act on grounds generally applicable to the Classes, thereby making appropriate final injunctive relief, corresponding declaratory relief, or final equitable relief with respect to the class as a whole.

///

///

SANTA BARBARA, CALIFORNIA 93101

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

VIOLATIONS ALLEGED

COUNT I

VIOLATION OF THE FLORIDA DECEPTIVE AND UNFAIR TRADE PRACTICES ACT, ("FDUTPA")

Fla. Stat. §§ 501.201, et seq.

(By Plaintiff Freeman on Behalf of the Florida Class)

- 151. Plaintiff Freeman and the Florida Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 152. Plaintiff Freeman brings this claim on behalf of himself and on behalf of the Florida Class against Defendants.
- 153. The Florida Deceptive and Unfair Trade Practices Act ("FDUTPA") prohibits "[u]nfair methods of competition, unconscionable acts or practices, and unfair or deceptive acts or practices in the conduct of any trade or commerce." Fla. Stat. § 501.204(1). Defendants engaged in unfair and deceptive practices that violated the FDUTPA as described above.
- 154. Defendants engaged in "trade or commerce" in Florida within the meaning of the FDUTPA. See Fla. Stat. § 501.203(8).
- 155. Defendants caused to be made or disseminated through Florida and the United States, through advertising, marketing and other publications, statements that were untrue or misleading, and which were known, or which by the exercise of reasonable care should have been known to Defendants, to be untrue and misleading to consumers, including Plaintiff Freeman and the other Florida Class Members and otherwise engaged in activities with a tendency or capacity to deceive.
- 156. In violation of the FDUTPA, Defendants employed unfair and deceptive acts or practices, fraud, false pretense, misrepresentation, or concealment, suppression or omission of a material fact with intent that others rely upon such concealment, suppression or omission, in connection with the sale and/or lease of Class Vehicles. Defendants knowingly concealed, suppressed and omitted materials facts regarding the

Sealant Defect and misrepresented the standard, quality, or grade of the Class Vehicles, which directly caused harm to Plaintiff Freeman and the Florida Class.

157. Defendants actively suppressed the fact that Class Vehicles contain the Sealant Defect and present a safety hazard because of materials, workmanship, design, and/or manufacturing defects. Further, Defendants employed unfair and deceptive trade practices by failing to provide repairs of the Sealant Defect or replacement of Class Vehicles due to the Defect within a reasonable time in violation of the FDUTPA. Defendants also breached their warranties as alleged above in violation of the FDUTPA.

158. As alleged above, Defendants have known of the Sealant Defect contained in the Class Vehicles for years. Prior to selling and leasing the Class Vehicles, Defendants knew or should have known the Class Vehicles contained the Sealant Defect due to pre-production testing, quality control audits, and failure mode analysis. Defendants also should have known of the Defect from the complaints and service requests they received from Class Members and dealers, from their own investigation, and from repairs and/or replacements of the tailgate control module, and from other internal sources. Defendants, nevertheless, failed to disclose and actively concealed the dangers and risks posed by the Class Vehicles and the Defect.

159. Defendants' unfair and deceptive trade practices were likely intended to deceive a reasonable consumer. Plaintiff Freeman and members of the Florida Class had no reasonable way to know that the Class Vehicles contained the Sealant Defect, were defective in workmanship and/or manufacture and posed a serious and significant safety risk. Defendants possessed superior knowledge as to the quality and characteristics of the Class Vehicles, including the Defect within their vehicles and its associated safety risks, and any reasonable consumer would have relied on Defendants' misrepresentations and omissions, as Plaintiff Freeman and members of the Florida Class did.

27 | ///

///

SANTA BARBARA, CALIFORNIA 93101

- 160. Defendants intentionally and knowingly misrepresented material facts and omitted material facts regarding the Class Vehicles and the Defect present in Class Vehicles with an intent to mislead Plaintiff Freeman and the Florida Class.
- 161. Defendants knew or should have known that their conduct violated the FDUTPA.
- 162. Defendants owed Plaintiff Freeman and the Florida Class a duty to disclose the true safety and reliability of the Class Vehicles and the existence of the Defect because Defendants, possessed exclusive knowledge of the Sealant Defect; intentionally concealed and omitted the foregoing from Plaintiff Freeman and the Florida Class, and made incomplete representations about the safety and reliability of the foregoing facts generally, while purposefully withholding material facts from Plaintiff Freeman and the Florida Class that contradicted these representations, *interalia*, that a Sealant Defect existed at the time of sale or lease.
- 163. Plaintiff Freeman and the other Florida Class Members have suffered an injury in fact, including the loss of money or property, as a result of Defendants' unfair, unlawful, and/or deceptive practices. In purchasing or leasing their Class Vehicles, Plaintiff Freeman and the other Florida Class Members relied on the misrepresentations and/or omissions of Defendants with respect to the safety and reliability of the Class Vehicles. Defendants' representations were untrue because the Class Vehicles are distributed with defective body seam seals that can cause failure of the tailgate control module. Had Plaintiff Freeman and the other Florida Class Members known of the Sealant Defect, they would not have purchased or leased their Class Vehicles and/or paid as much for them. Accordingly, Plaintiff Freeman and the other Florida Class Members overpaid for their Class Vehicles and did not receive the benefit of their bargain.
- 164. All of the wrongful conduct alleged herein occurred, and continues to occur, in the conduct of Defendants' businesses. Defendants' wrongful conduct is part

of a pattern or generalized course of conduct that is still perpetuated and repeated, both in the state of Florida and nationwide.

165. Plaintiff Freeman, individually and on behalf of the other Florida Class Members, requests that this Court enter such orders or judgments as may be necessary to enjoin Defendants from continuing their unfair, unlawful, and/or deceptive practices and to provide declaratory relief, attorneys' fees, and any other just and proper relief available under the FDUTPA.

COUNT II BREACH OF EXPRESS WARRANTY (On Behalf of the Nationwide and State Classes)

- 166. Plaintiffs and the Classes incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 167. Defendants expressly warranted that the Class Vehicles were of high quality and, at a minimum, would actually work properly. Honda also expressly warranted that it would repair and/or replace defects in material and/or workmanship free of charge that occurred during the New Vehicle Limited Warranty and certified pre-owned ("CPO") warranty periods.
- 168. Defendants breached these warranties by selling to Plaintiffs and Class members the Class Vehicles with the Sealant Defect, which are not of high quality, and which fail prematurely and/or fail to function properly.
- 169. As a result of the Defendants' actions, Plaintiffs and Class members have suffered economic damages including but not limited to costly repairs, loss of vehicle use, substantial loss in value and resale value of the vehicles, and other related damage.
- 170. Defendants' attempt to disclaim or limit these express warranties vis-à-vis consumers is unconscionable and unenforceable under the circumstances here. Specifically, Defendants' warranty limitations are unenforceable because it knowingly sold a defective product without informing consumers about the manufacturing and/or material defect. Furthermore, Defendants continue to charge Class members for both

replacing the tailgate control module and for repairing the defective body seam seal – if it repairs it at all – when in fact such repairs are actually necessitated because of Defendants' defective product.

- 171. The time limits contained in Defendants' warranty periods were also unconscionable and inadequate to protect Plaintiffs and members of the Class. Among other things, Plaintiffs and Class members had no meaningful choice in determining these time limitations, the terms of which unreasonably favored Defendants. A gross disparity in bargaining power existed between Honda and the Class members, and Honda knew or should have known that the Class Vehicles were defective at the time of sale and would fail well before their useful lives.
- 172. Plaintiffs provided written notice of Honda's breach of warranties, as well as the other claims asserted herein, on October 21, 2024, February 21, 2025, and February 26, 2025.
- 173. Plaintiffs and the Class members have complied with all obligations under the warranties, or otherwise have been excused from performance of said obligations as a result of Defendants' conduct described herein.

COUNT III BREACH OF IMPLIED WARRANTY (On Behalf of the Nationwide and State Classes)

- 174. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 175. A warranty that the Class Vehicles were in merchantable condition is implied by law.
- 176. These Class Vehicles, when sold and at all times thereafter, were not in merchantable condition and are not fit for the ordinary purpose for which cars are used. Specifically, the Class Vehicles are inherently defective in that there are defects in the Class Vehicles' body seam seals, which are not of high quality, and which fail prematurely and/or fail to function properly.

E, STIRLING, HALE, IMILLER & SWE 33 WESTMISSION STREET, SUTTE 201 SANTA BARBARA, CALIFORNIA 93101 1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

177. Honda was provided notice of these issues by numerous informal and formal complaints filed against them, including the instant Complaint, and by numerous individual letters and communications sent by Plaintiffs and other Class members.

178. As a direct and proximate result of Defendant's breach of the warranties of merchantability, Plaintiffs and the other Class members have been damaged in an amount to be proven at trial.

COUNT IV COMMON LAW FRAUD (On Behalf of the Nationwide and State Classses)

- 179. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 180. Defendants made material omissions concerning a presently existing or past fact. For example, Defendants did not fully and truthfully disclose to their customers the defective nature of the Class Vehicles' body seam seals, which was not readily discoverable until after the Vehicles were purchased. As a result, Plaintiffs and the other Class members were fraudulently induced to lease and/or purchase the Class Vehicles with the said Sealant Defect and all of the resultant problems.
- 181. These omissions were made by Honda with knowledge of their falsity, and with the intent that Plaintiffs and Class members rely upon them.
- 182. Plaintiffs and Class members reasonably relied on these omissions, and suffered damages as a result.

COUNT V BREACH OF THE DUTY OF GOOD FAITH AND FAIR DEALING (On Behalf of the State Classes)

- 183. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein.
- 184. Plaintiff Freeman brings this claim on behalf of himself and on behalf of the Florida Class against Defendants. Plaintiff Sullivan brings this claim on behalf of himself and on behalf of the New Jersey Class against Defendants. Plaintiffs Riker and

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

Ameti bring this claim on behalf of themselves and on behalf of the Washington Class against Defendants.

- 185. Every contract in Florida, New Jersey, and Washington contains an implied covenant of good faith and fair dealing. The implied covenant of good faith and fair dealing is an independent duty and may be breached even if there is no breach of a contract's express terms.
- 186. Defendants breached the covenant of good faith and fair dealing through malicious conduct by, *inter alia*, failing to notify Plaintiffs and the Class members of the Sealant Defect in the Class Vehicles, and failing to fully and properly repair this defect.
- 187. Defendants acted in bad faith and/or with a malicious motive to deny Plaintiffs and Class members some benefit of the bargain originally intended by the parties, thereby causing them injuries in an amount to be determined at trial.

COUNT VI UNJUST ENRICHMENT (On Behalf of the Nationwide and the States Classes)

- 188. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as though fully set forth at length herein. This count is pled in the alternative to the contract-based claims.
 - 189. Plaintiffs and the members of the Class conferred a benefit on Defendants.
 - 190. Defendants had knowledge that this benefit was conferred upon them.
- 191. Defendants have been and continue to be unjustly enriched at the expense of Plaintiffs, and their retention of this benefit under the circumstances would be inequitable.

COUNT VII

VIOLATION OF THE NEW JERSEY CONSUMER FRAUD ACT, ("NJCFA")

N.J. Stat. Ann. §§ 56:8-1, et seq.

(By Plaintiff Sullivan on Babalf of the New Jersey Class)

(By Plaintiff Sullivan on Behalf of the New Jersey Class)

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

- 192. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as through fully set forth at length herein.
- 193. Plaintiff Sullivan brings this claim on behalf of himself and on behalf of the New Jersey Class against Defendants.
- 194. The New Jersey Consumer Fraud Act, N.J. Stat. Ann. §§ 56:8-1, et seq. ("NJCFA") protects consumers against "any unconscionable commercial practice, deception, fraud, false pretense, false promise, misrepresentation, or the knowing, concealment, suppression, or omission of any material fact with intent that others rely upon such concealment, suppression or omission, in connection with the sale or advertisement of any merchandise " N.J. Stat. Ann. § 56:8-2.
- 195. Plaintiff Sullivan and the New Jersey Class Members are consumers who purchased or leased Class Vehicles.
- 196. In the course of Honda's business, it knowingly concealed, suppressed, and omitted the fact that the Class Vehicles suffer from the Sealant Defect and present a safety hazard because of materials, workmanship, design, and/or manufacturing defects. Further, Defendants employed unfair and deceptive trade practices by failing to provide repairs of the Sealant Defect or replacement of Class Vehicles at no cost to consumers. Honda's conduct was done with the intent that Plaintiff Sullivan and the New Jersey Class Members rely upon that concealment, suppression, and omission when making their purchasing decisions.
- 197. The existence of the Sealant Defect is material because the Sealant Defect poses a serious and significant safety risk and impacts the reliability and safety of the Class Vehicles.
 - 198. Honda has engaged in unfair and deceptive trade practices, including:
 - a. representing that the Class Vehicles have characteristics, uses, benefits, and qualities which they do not have;
 - b. representing that the Class Vehicles are of a particular standard and quality when they are not;

	#:183
c.	advertising the Class Vehicles with the intent to not sell them as advertised;
	and
d.	otherwise engaging in conduct likely to deceive.
199.	Honda's actions as set forth above occurred in the conduct of trade or
commerce.	
200.	Honda's conduct caused Plaintiff Sullivan and the New Jersey Class
Members to	suffer an ascertainable loss. Plaintiff Sullivan and the other New Jersey

200. Honda's conduct caused Plaintiff Sullivan and the New Jersey Class Members to suffer an ascertainable loss. Plaintiff Sullivan and the other New Jersey Class Members purchased vehicles they otherwise would not have, overpaid for their vehicles, did not receive the benefit of their bargain, and their vehicles suffered a diminution in value. Plaintiff Sullivan and the New Jersey Class Members have also incurred and will continue to incur costs for necessary repairs to their vehicles as a result of the Defect.

201. Plaintiff Sullivan's and other New Jersey Class Members' damages are the direct and foreseeable result of Defendants' unlawful conduct. Had the Sealant Defect in the Class Vehicles been disclosed, consumers would not have purchased or would have paid less for them and would have been spared the subsequent expenses described herein.

202. Pursuant to N.J. Stat. Ann. § 56:8-20, the New Jersey Attorney General will be served with a copy of this Complaint.

COUNT VIII VIOLATION OF THE WASHINGTON CONSUMER PROTECTION ACT, ("WCPA")

Wash. Rev. Code §§ 19.86.010, et seq. (By Plaintiffs Riker and Ameti on Behalf of the Washington Class)

- 203. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as through fully set forth at length herein.
- 204. Plaintiffs Riker and Ameti bring this claim on behalf of themselves and on behalf of the Washington Class against Defendants.

205. Plaintiffs Riker and Ameti and Washington Class Members are "persons" within the meaning of the WCPA, Wash. Rev. Code § 19.86.010(1).

206. Defendants are "persons" within the meaning of the Washington Consumer Protection Act ("WCPA"), Wash. Rev. Code § 19.86.010(1).

207. Defendants conduct "trade" and "commerce" within the meaning of the WCPA, WRC § 19.86.010(2).

208. Defendants' actions are unfair and/or deceptive within the meaning of the WCPA in that Defendants have engaged in deception, fraud, unfair practices, and concealment by the conduct, statements, and omissions described above, and by knowingly and intentionally concealing from Plaintiffs Riker and Ameti and the Washington Class Members that the Class Vehicles suffer from the Sealant Defect and present a safety hazard because of materials, workmanship, design, and/or manufacturing defects. Further, Defendants employed unfair and deceptive trade practices by failing to provide repairs of the Sealant Defect or replacement of Class Vehicles at no cost to consumers. Honda's conduct was done with the intent that Plaintiffs Riker and Ameti and the Washington Class Members rely upon that concealment, suppression, and omission when making their purchasing decisions.

209. Defendants' unfair or deceptive acts or practices have occurred in their trade or business, and Defendants were and are capable of deceiving a substantial portion of the public.

210. Honda's conduct caused Plaintiffs Riker and Ameti and the Washington Class Members to suffer an ascertainable loss. Plaintiffs Riker and Ameti and the other Washington Class Members purchased vehicles they otherwise would not have, overpaid for their vehicles, did not receive the benefit of their bargain, and their vehicles suffered a diminution in value. Plaintiffs Riker and Ameti and the Washington Class Members have also incurred and will continue to incur costs for necessary repairs to their vehicles as a result of the Defect.

- 211. Plaintiffs Riker and Ameti's and other Washington Class Members' damages are the direct and foreseeable result of Defendants' unlawful conduct. Had the Sealant Defect in the Class Vehicles been disclosed, consumers would not have purchased or would have paid less for them and would have been spared the subsequent expenses described herein.
- 212. Defendants' general course of conduct has an impact on the public interest, and the acts complained of herein are ongoing and/or have a substantial likelihood of being repeated.
- 213. As a direct and proximate result of Defendants' actions described above, Plaintiffs Riker and Ameti and the Washington Class Members have been injured in fact and suffered damages, and seek relief in the form of actual damages, treble damages, and reasonable attorneys' fees, pursuant to Wash. Rev. Code § 19.86.090.

VIOLATION OF THE MARYLAND CONSUMER PROTECTION ACT Md. Code Comm. Law §§ 13-301 et seq. (By Plaintiff Hannah on Behalf of the Maryland Class)

- 214. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as through fully set forth at length herein.
- 215. Plaintiff Hannah brings this claim individually and on behalf of the Maryland Class against Defendants.
 - 216. Honda is a person as defined by Md. Comm. Code § 13-101(h).
- 217. Honda's conduct as alleged herein related to "sales," "offers for sale," or "bailment" as defined by Md. Comm. Code § 13-101(i) and § 13-303.
- 218. Plaintiff Hannah and the Maryland Class members are "consumers" as defined by Md. Comm. Code § 13-101(c).
- 219. Defendants advertise, offer, or sell "consumer goods or "consumer services" as defined by Md. Comm. Code § 13-101(d).

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

- 220. Defendants advertised, offered, or sold goods or services in Maryland and engaged in trade or commerce directly or indirectly affecting the people of Maryland.
- 221. Defendants engaged in unfair and deceptive trade practices, in violation of Md. Comm. Code § 13-301, including:
 - a. False or misleading oral or written representations that have the capacity, tendency, or effect of deceiving or misleading consumers;
 - b. Representing that consumer goods or services have a characteristic that they do not have;
 - c. Representing that consumer goods or services are of a particular standard, quality, or grade that they are not;
 - d. Failing to state a material fact where the failure deceives or tends to deceive;
 - e. Advertising or offering consumer goods or services without intent to sell, lease, or rent them as advertised or offer; and
 - f. Deception, fraud, false pretense, false premise, misrepresentation, or knowing concealment, suppression, or omission of any material fact with the intent that a consumer rely on the same in connection with the promotion or sale of consumer goods or services of the subsequent performance with respect to an agreement, sale, lease, or rental.
- 222. Defendants engaged in these unfair and deceptive trade practices in connection with offering for sale or selling consumer goods or services in violation of Md. Comm. Code § 13-303.
- 223. Defendants' representations and omissions were material because they were likely to deceive reasonable consumers.
- 224. Defendants intended to mislead Plaintiff Murphy and the Maryland Class members and induce them to rely on their misrepresentations and omissions.
- 225. Defendants should have disclosed the Sealant Defect to Plaintiff Hannah and the Maryland Class because they were in a superior position to know the true facts

2

3

4

5

6

7

8

9

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

28

related to the Sealant Defect, and Plaintiff Hannah and Maryland Class members could not reasonably be expected to learn or discover the true facts related to this Sealant Defect.

226. Defendants, by the conduct, statements, and omissions described above, also knowingly and intentionally concealed from Plaintiff Hannah and the Maryland Class members that Class Vehicles suffer from the Sealant Defect (and the costs, safety risks, and diminished value of the Class Vehicles as a result of this problem).

227. These acts and practices have deceived Plaintiff Hannah and are likely to deceive the public. Defendants, by the conduct, statements, and omissions described above, and by knowingly and intentionally concealing from Plaintiff Hannah and the Maryland Class members that the Class Vehicles suffer from the Sealant Defect (and the costs, safety risks, and diminished value of the Class Vehicles as a result of this problem), breached their duties to disclose these facts, violated the MCPA, and caused injuries to Plaintiff Hannah and the Maryland Class members. The omissions and acts of concealment by Defendants pertained to information that was material to Plaintiff Hannah and Maryland Class members, as it would have been to all reasonable consumers.

The injuries suffered by Plaintiff Hannah and the Maryland Class members 228. are greatly outweighed by any potential countervailing benefit to consumers or to competition, nor are they injuries that Plaintiff Hannah and the Maryland Class members should have reasonably avoided.

229. Defendants' conduct proximately caused injuries to Plaintiff Hannah and other Maryland Class members. Had Plaintiff Hannah and the Class known about the defective nature of the Class Vehicles, they would not have purchased the Class Vehicles, would have paid less for them or would have avoided the extensive repair costs associated therewith.

27

///

33 WEST MISSION STREET, SUITE 201 SANTA BARBARA, CALIFORNIA 93101 1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

230. Plaintiff Hannah and the Maryland Class members seek all monetary and non-monetary relief allowed by law, including damages, disgorgement, injunctive relief, and attorneys' fees and costs.

COUNT X VIOLATION OF THE CALIFORNIA UNFAIR COMPETITION LAW ("UCL")

Cal. Bus. & Prof. Code §§ 17200-17210 (By Plaintiff Angulo on Behalf of the California Class)

- 231. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as through fully set forth at length herein.
- 232. The UCL proscribes acts of unfair competition, including "any unlawful, unfair or fraudulent business act or practice and unfair, deceptive, untrue or misleading advertising." Cal. Bus. & Prof. Code § 17200. Honda's conduct violates each of these prohibitions.

Unlawful Conduct

233. Honda's conduct is unlawful, in violation of the UCL, because, as set forth herein, it violates the Song-Beverly Consumer Warranty Act and the CLRA.

Unfair Conduct

- 234. Honda's conduct is unfair because it violated California public policy, legislatively declared in the Song-Beverly Consumer Warranty Act, which requires a manufacturer to ensure that goods it places on the market are fit for their ordinary and intended purposes.
- 235. Honda acted in an immoral, unethical, oppressive, and unscrupulous manner, in at least the following respects:
 - a. Selling Plaintiff Angulo and California Class members defective Class Vehicles;

/// ///

4

6

8

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 201

22

23 24

26

27

25

28

- b. Failing to disclose the Sealant Defect despite the opportunity to do so in numerous locations that people in the market for a vehicle would be likely to encounter;
- c. Directing and furnishing replacement parts it knew would not adequately remedy the defect, and repairing defective parts with more defective parts and otherwise failing to adequately remedy the Sealant Defect during the warranty period;
- d. Refusing to repair or replace the Class Vehicles when the known Sealant Defect manifested outside the warranty period;
- e. Failing to exercise adequate quality control and due diligence over the Class Vehicles before placing them on the market; and
- f. Failing to acknowledge the scope and severity of the Sealant Defect, refusing to acknowledge the Class Vehicles are defective, and failing to provide adequate relief to Plaintiff Angulo and California Class members.
- The gravity of the harm resulting from Honda's unfair conduct outweighs any potential utility of the conduct. The practice of selling defective Class Vehicles without providing an adequate remedy to cure the Sealant Defect harms the public at large and is part of a common and uniform course of wrongful conduct.
- 237. There are reasonably available alternatives that would further Honda's business interests of increasing sales and preventing false warranty claims. For example, Honda could have: (a) acknowledged the Sealant Defect and provided a permanent, effective fix for the Sealant Defect; and/or (b) disclosed the Sealant Defect prior to prospective consumers' purchases.
- 238. The harm from Honda's unfair conduct was not reasonably avoidable by consumers. The Class Vehicles all suffer from the Sealant Defect, and Honda has failed to disclose it. Plaintiff Angulo and California Class members did not know of, and had no reasonable means of discovering, the Sealant Defect.

Fraudulent Conduct

- 239. Honda's conduct is fraudulent in violation of the UCL. Honda's fraudulent acts include knowingly and intentionally concealing from Plaintiff Angulo and the California Class members the existence of the Sealant Defect and falsely marketing and misrepresenting the Class Vehicles as being functional and not possessing a defect that would render the power tailgates inoperable.
- 240. Honda's misrepresentations and omissions alleged herein caused Plaintiff Angulo and the California Class members to purchase or lease their Class Vehicles or pay more than they would have had Honda disclosed the Sealant Defect.
- 241. At all relevant times, Honda had a duty to disclose the Defect because it had superior and exclusive knowledge of the Defect, which affects the central functionality of the vehicle and creates a safety risk for drivers and passengers, and because Honda made partial representations about the reliability, quality, and safety of the Class Vehicles but failed to fully disclose the Sealant Defect.
- 242. Accordingly, Plaintiff Angulo and California Class members have suffered injury in fact, including lost money or property, as a result of Honda's unlawful, unfair, and fraudulent acts. Absent these acts, Plaintiff Angulo and California Class members would not have purchased or leased their Class Vehicles at the prices they paid or would not have purchased or leased them at all.
- 243. Plaintiff Angulo seeks appropriate relief under the UCL, including such orders as may be necessary: (a) to enjoin Honda from continuing its unlawful, unfair, and fraudulent acts or practices, and (b) to restore Plaintiff Angulo and California Class members any money Honda acquired by its unfair competition, including restitution. Plaintiff Angulo also seeks reasonable attorneys' fees and expenses under applicable law.

COUNT XI VIOLATION OF THE CALIFORNIA CONSUMERS LEGAL REMEDIES ACT ("CLRA") Cal. Civ. Code §§ 1750-1785

(By Plaintiff Angulo on Behalf of the California Class)

- 244. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as through fully set forth at length herein.
- 245. Plaintiff Angulo and the members of the California Class are "consumers" as defined under the CLRA. See Cal. Civ. Code § 1761(d).
- 246. Honda is a "person" as defined under the CLRA. See Cal. Civ. Code § 1761(c).
- 247. Class Vehicles are "goods" as defined under the CLRA. See Cal. Civ. Code § 1761(a).
- 248. The CLRA proscribes "unfair methods of competition and unfair or deceptive acts or practices undertaken by any person in a transaction intended to result or which results in the sale or lease of goods or services to any consumer." Cal. Civ. Code § 1770(a).
- 249. Honda engaged in unfair and deceptive acts in violation of the CLRA by the practices described above and by knowingly and intentionally concealing from Plaintiff Angulo and the California Class members that the Class Vehicles suffer from the Sealant Defect (and the costs, risks, and diminished value of the Class Vehicles as a result of this Defect). Honda's conduct violated at least the following enumerated CLRA provisions:
 - a. Honda represented that the Class Vehicles have characteristics, uses, or benefits that they do not have, which is in violation of section 1770(a)(5);
 - b. Honda represented that the Class Vehicles are of a particular standard, quality, or grade when, in fact, they are not, which is in violation of section 1770(a)(7);
 - c. Honda advertises its Class Vehicles with the intent not to sell them as advertised, which is in violation of section 1770(a)(9);

4

9

NYE, STIRLING, HALE, MILLER & SWEET

33 WEST MISSION STREET, SUITE 201

25

26

27 28

- d. Honda represents that its Class Vehicles have been supplied in accordance with a previous representation when they have not, which is in violation of section 1770(a)(16); and
- e. Honda inserts an unconscionable provision into its warranty in violation of section 1770(a)(19).
- 250. Honda's unfair or deceptive acts or practices occurred repeatedly in its trade or business and were capable of deceiving a substantial portion of the purchasing public.
- Honda knew, should have known, or was reckless in not knowing that the Class Vehicles were defective, would fail prematurely, and were not suitable for their intended use.
- 252. Honda was under a duty to Plaintiff Angulo and the California Class members to disclose the defective nature of the Class Vehicles and the Sealant Defect because:
 - a. Honda knew of but actively concealed the Sealant Defect from Plaintiff Angulo and the California Class;
 - b. Honda was in a superior and exclusive position to know the true facts about the Sealant Defect, which affects the central functionality of the vehicle and poses safety concerns, and Plaintiff Angulo and the California Class members could not reasonably have been expected to discover that the Class Vehicles contained the Sealant Defect until it manifested, which Honda knew; and
 - c. Honda made partial representations regarding the reliability, safety, and quality but suppressed material facts regarding the Sealant Defect.
- 253. The facts that Honda misrepresented to and concealed from Plaintiff Angulo and the other California Class members are material because a reasonable consumer would have considered them to be important in deciding whether to purchase their Class Vehicles or pay a lesser price for them.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

- The Sealant Defect poses a serious safety defect and affects the central functionality of a vehicle because it renders the vehicle inoperable.
- 255. In failing to disclose the material Sealant Defect, Honda has knowingly and intentionally concealed material facts in breach of its duty to disclose.
- 256. Plaintiff Angulo and the California Class have suffered injury in fact and actual damages resulting from Honda's material misrepresentations and omissions, including by paying an inflated purchase price for their Class Vehicles and incurring additional out-of-pocket expenses to deal with the Sealant Defect. Had Plaintiff Angulo and the California Class known about the defective nature of the Class Vehicles and the Sealant Defect, they would not have purchased or leased their Class Vehicles or would have paid less in doing so.
- 257. As a direct and proximate result of Honda's unfair and deceptive conduct, Plaintiff Angulo and the California Class members have been harmed.
- 258. Pursuant to Cal. Civ. Code § 1782(a), Plaintiff Angulo sent a letter to Honda notifying it of its CLRA violations and providing them with an opportunity to correct their business practices. If Honda does not correct its business practices, Plaintiff Angulo will amend (or seek leave to amend) the complaint to add claims for monetary relief, including for actual, restitutionary, and punitive damages under the CLRA.
- 259. Pursuant to Cal. Civ. Code § 1780(a), Plaintiff Angulo, individually and on behalf of the California Class, seeks injunctive relief for Honda's violation of the CLRA.
- 260. Additionally, pursuant to Cal. Civ. Code §§ 1780 and 1781, Plaintiff Angulo, individually and on behalf of the California Class, seeks compensatory and punitive damages under the CLRA and to recover their attorneys' fees and costs.
- 261. Plaintiff Angulo's CLRA venue declaration is attached as an exhibit to this complaint in accordance with Cal. Civ. Code § 1780(d).

///

33 WEST MISSION STREET, SUITE 201 SANTA BARBARA, CALIFORNIA 93101

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

CO	UNT	XII
CO	UINI	$\Lambda \Pi$

VIOLATION OF THE SONG-BEVERLY CONSUMER WARRANTY ACT FOR BREACH OF IMPLIED WARRANTY

Cal. Civ. Code §§ 1790-1795.8

(By Plaintiff Angulo on Behalf of the California Class)

- 262. Plaintiffs and the Class incorporate by reference each preceding and succeeding paragraph as through fully set forth at length herein.
- 263. Plaintiff Angulo and the California Class members who purchased or leased the Class Vehicles are "buyers" within the meaning of Cal. Civ. Code. § 1791(b).
- 264. The class vehicles are "consumer goods" within the meaning of Cal. Civ. Code § 1791(a).
- 265. Honda is a "manufacturer" of the Class Vehicles within the meaning of Cal. Civ. Code § 1791(i).
- 266. Honda impliedly warranted to Plaintiff Angulo and the California Class members that Class Vehicles were "merchantable" within the meaning of Cal. Civ. Code §§ 1791.1(a) & 1792.
- 267. Section 1791.1(a) provides that: "Implied warranty of merchantability" or "implied warranty that goods are merchantable" means that the consumer goods must meet each of the following:
 - (1) Pass without objection in the trade under the contract description.
 - (2) Are fit for the ordinary purposes for which such goods are used.
 - (3) Are adequately contained, packaged, and labeled.
 - (4) Conform to the promises or affirmations of fact made on the container or label.
- The Sealant Defect in the Class Vehicles is present in them when sold and 268. substantially certain to manifest. The Class Vehicles would not pass without objection in the automotive trade because the Defect causes the power tailgate to fail to operate

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

1

2

as intended. The Defect thus affects the central functionality of the power tailgate, leading to thousands of dollars in repair expenses and inconvenient service calls.

- 269. Because the Sealant Defect prevents Class Members from accessing the rear of the vehicle, the Class Vehicles are not fit for the ordinary purposes for which such vehicles are used.
- 270. Class Vehicles are not adequately labeled because the labeling fails to disclose the Sealant Defect and does not advise the California Class members of this Sealant Defect.
- 271. Any attempt by Honda to disclaim its implied warranty obligations under the Song-Beverly Act is ineffective due to its failure to adhere to Sections 1792.3 and 1792.4. Those sections of the Civil Code provide that, in order to validly disclaim the implied warranty of merchantability, a manufacturer must "in simple and concise language" state each of the following: "(1) The goods are being sold on an 'as is' or 'with all faults' basis. (2) The entire risk as to the quality and performance of the goods is with the buyer. (3) Should the goods prove defective following their purchase, the buyer and not the manufacturer, distributor, or retailer assumes the entire cost of all necessary servicing or repair." Cal. Civ. Code § 1792.4(a). Honda's attempted implied warranty disclaimer does not conform to these requirements.
- 272. The Sealant Defect deprived Plaintiff Angulo and the California Class members of the benefit of their bargain and resulted in Class Vehicles being worth less than what Plaintiff Angulo and other California Class members paid.
- 273. As a direct and proximate result of Honda's breach of its implied warranties, Plaintiff Angulo and California Class members received goods that contain a defect that substantially impairs their value. Plaintiff Angulo and the California Class members have been damaged by the diminished value of the vehicles, the vehicles' malfunctioning, out-of-pocket costs incurred, and actual and potential increased maintenance and repair costs.

2

3

4

5

6

7

8

9

10

11

14

15

16

19

20

21

22

23

24

25

26

27

28

274. Under Cal. Civ. Code §§ 1791.1(d) & 1794, Plaintiff Angulo and California Class members are entitled to damages and other legal and equitable relief, including, inter alia, benefit-of-the-bargain damages, overpayment or diminution in value of their Class Vehicles, and reasonable attorneys' fees and costs.

PRAYER FOR RELIEF

WHEREFORE, Plaintiffs, on behalf of themselves and members of the Classes, respectfully request that this Court:

- determine that the claims alleged herein may be maintained as a A. class action under Rule 23 of the Federal Rules of Civil Procedure, and issue an order certifying the Classes as defined above;
- В. appoint Plaintiffs as the representatives of the Class and their counsel as Class Counsel;
- C. award all actual, general, special, incidental, statutory, punitive, and consequential damages to which Plaintiffs and Class members are entitled;
- award pre-judgment and post-judgment interest on such monetary D. relief;
- E. grant appropriate injunctive and/or declaratory relief, including, without limitation, an order that requires Honda to repair, recall, and/or replace the Class Vehicles and to extend the applicable warranties to a reasonable period of time, or, at a minimum, to provide Plaintiffs and Class members with appropriate curative notice regarding the existence and cause of the manufacturing defect;
- F. award reasonable attorney's fees and costs; and
- G. grant such further relief that this Court deems appropriate. Signatures below.

	Case	e 2:24-cv-09153-HDV-AS	Document 18 Filed 02/28/25 Page 90 of 91 Page ID #:197			
	1					
	2	Dated: February 28, 2025	NYE, STIRLING, HALE, MILLER & SWEET, LLP			
	3		By: /s/ Alison M. Bernal			
	4		Alison M. Bernal, Esq. (SBN 264629) alison@nshmlaw.com			
	5	33 West Mission Street, Suite 201 Santa Barbara, CA 93101				
	6		Telephone: (805) 963-2345 Facsimile: (805) 284-9590			
	7		1 desimile. (003) 204 7370			
	8		Matthew D. Schelkopf (<i>pro hac vice</i> forthcoming) mds@sstriallawyers.com			
	9		Joseph B. Kenney (<i>pro hac vice</i> forthcoming)			
10			jbk@sstriallawyers.com SAUDER SCHELKOPF LLC 1109 Lancaster Avenue			
ΈΤ	11		Berwyn, PA 19312			
NYE, STIRLING, HALE, MILLER & SWEET 33 WEST MISSION STREET, SUITE 201 SANTA BARBARA, CALIFORNIA 93101 61 12 14 15 16 17 18 19 19 10 10 11 11 11 11 11 11 11 11 11 11 11	12		Telephone: (610) 200-0581 Facsimile: (610) 421-1326			
	13		Attorneys for Plaintiffs and the putative classes			
	14					
	15					
	16	DEMAND FOR JURY TRIAL				
	17	Plaintiffs hereby demand a jury trial for all claims so triable.				
	18	Data de Fahrmany 20, 2026	NIVE CTIDI INC. HALE MILLED & CWEET LLD			
	19	Dated: February 28, 2025				
	20		By: /s/ Alison M. Bernal Alison M. Bernal Fag. (SBN 264620)			
	21	Alison M. Bernal, Esq. (SBN 264629) alison@nshmlaw.com				
	22		33 West Mission Street, Suite 201 Santa Barbara, CA 93101			
	23		Telephone: (805) 963-2345 Facsimile: (805) 284-9590			
2	24		Signatures continued below.			
	25					
	26					
	27					
	28					
			90			
	FIRST AMENDED CLASS ACTION COMPLAINT					